

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR  
Chase Energy, Inc.

3. ADDRESS OF OPERATOR  
c/o Allen Consulting, Inc. 2501 E. 20th, Farmington

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface  
2470' FSL, 1570' FEL

BUREAU OF LAND MANAGEMENT

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, AT, GR, etc.)

5100' GR

5. LEASE DESIGNATION AND SERIAL NO.

14-23-0503-639

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

King Kong

9. WELL NO.

19

10. FIELD AND POOL, OR WILDCAT

Salt Creek Dakota

11. SEC., T., R., W., OR BLK. AND  
SURVEY OR AREA

Sec. 4 T30N R17W

12. COUNTY OR PARISH 13. STATE

San Juan New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACURE TREAT

MULTIPLE COMPLETE

FRACURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

(Other) Return to Production

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

It is intended to return the above captioned well to production following the procedure outlined below.

1. MIRU.
2. CO to TD.
3. Run pump, rods and tbq.
4. Set production equipment.
5. Test well.
6. Release rig.

Notify this office w/in 5 days of production start-up, also report this on Monthly Report of Operations

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

DATE MAR 20 1985

NMOC

\*See Instructions on Reverse Side