	Form api
MIT IN TRIPLICATE®	
st lustidefione on se-	G. LEASE DESIGNAT

Form	approvie	d.		
Budge	t Buren	μ No.	42-R	1421
LEADE DESIG				

Water Const

	UNITED STATES MENT OF THE INTER GEOLOGICAL SURVEY		Budget Burea 5. LEASE DESIGNATION 14-20-0603 6. IF INDIAN, ALLOTTEE	4639
SUNDRY NO (Do not use this form for prop Use "APPLIC	TICES AND REPORTS	ON WELLS back to a different reservoir. proposals.)	Navajo Tri	
OIL CAS				
WELL WELL OTHER			8. FARM OR LEASE NAM	E
2. HAME OF OPERATOR			King Kong	
TASCO			9. WELL NO.	
	e 110, Farmington, N	'ew Mexico	Listed be	
4. LOCATION OF WELL (Report location	clearly and in accordance with an	State requirements.	10. FIELD AND POOL, OR	WILDCAT
See also space 17 below.) At surface		•	Salt Creek	
			11. SEC., T., R., M., OR B SURVEY OR AREA	LK. AND
		•		•
			4-30N-17-W	10.
14. PERMIT NO.	15. ELEVATIONS (Show whether D	OF, RT, GR, etc.)	12. COUNTY OR PARISH	
			San Juan	New Mexico
FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON® CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING COADAN Change of	EEPAIRING WALTERING CAABANDONMENDOWNERShip of multiple completion detion Report and Log for	ISING X
ment to this work.)	tionary dimed and con-	ent details, and give pertinent dates, actions and measured and true vertice	Induding actimated date	a of etarting ADT
Change from R. A. Ci	rane Jr. Box 356 Frui	tland New Mexico	Oct of	
Too: TASCO 501 Air	port dr. Suite 110 F	armington, New Mexico	87401	
•• •• •	79 It MOON DARKE	· · · · · · · · ·		
Wells . 3	E-4-T30N-R17W E-4-T30N-R17W			
13	F-4-T30N-R17W			
17	F-4-130N-R17W G-4-T30N-R17W			
15	G-4-T30N-R17W			
16	G-4-T30N-R17W		. 4	
10	G-4-T30N-R17W	·		는 함께 가를 가입다. 참 기가를 가를 다
21	H-4-T30N-R17W			
22	C_J		P.Trans	

AUG 2 COM.	
DATE 8-25-78	

(This space for Federal or State office use)

18. I bereby

8IGNED

19

certify what the foregoing is true and correct

G-4-T30N-R17W G-4-T30N-R17W G-4-T30N-R17W G-4-T30N-R17W K-4-T30N-R17W

TITLE

TITLE

Operator