Form 3160-5 [IIII] (June 1990)	ITED STATES NT OF THE INTERIOR	FORM APPROVED Budget Bureau No. 1004-0135
(A) IS MUREAU OF	MAND MANAGEMENT	Expires: March 31, 1993
A SA A SE	A'	5. Lease Designation and Serial No.
Do not use this form to contact the second	AND REPORTS ON WELLS	SF-081226 6. If Indian, Allottee or Tribe Name
Use "APPLICATION FO	rill or to deepen or reentry to a different reservoid DR PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE		NAVAJO 7. If Unit or CA, Agreement Designation
1. Type of Well	TINTIFEICATE	
Oil Gas Uther		HORSESHOE GALLUP UNIT
2. Name of Operator		8. Well Name and No.
ARCO Oil and Gas Company, Div. of Atlantic Richfield Co. 3. Address and Telephone No.		HORSESHOE GALLUP 297 9. API Well No.
1816 E. Mojave, Farmington, New Mexico 87401 (505) 325-7527 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		3004522097 10. Field and Pool, or Exploratory Area
		HORSESHOE GALLUP
		11. County or Parish, State
1550'FSL, 1250'FEL	SEC 4 T 20N D 4411	
· · · · · · · · · · · · · · · · · · ·	SEC 4, T-30N, R-16W	SAN JUAN NM
	(s) TO INDICATE NATURE OF NOTICE, REPO	ORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
Sub	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair Altering Casing	Water Shut-Off
	X Other Long Term SI	Conversion to Injection Dispose Water
	Il pertinent details, and give pertinent dates, including estimated date of startical denths for all markers and populations of the startical denths for all markers and populations.	(Note: Report results of multiple completion on Well
previously uneconomic long to production as market condition ARCO is selling it's working new owners are very interest with the recent increase in this well be maintained in the will be available, should fur	pectfully requests approval for exterwell. ARCO continues to find ways to erm shut-in wells and has returned so ons and production allowed. As you interest in the Horseshoe Gallup Uned in reactivating long term shut-in oil prices. For these reasons, ARCO he long term shut-in status so that the ture production tests indicate commentation waste of potentially usable well.	reactivate everal to are aware, it and the wells especially proposes that the wellbore rcial production. llbores and
14. I hereby certify that the foregoing is true and correct .		
Signed Corum	Con Don Lo	
(This space for Federal or State office use)	Title Sr. Prod Supr	Dute09/07/90
Approved by		APPROVED
Conditions of approval, if any:	Title	APPROVED AS AMENDED
		COD
Fitle 18 U.S.C. Section 1001, makes it a crime for any person is or representations as to any matter within its jurisdiction.	knowingly and willfully to make to any department or agency of the United	d States any false Actitions of Children statements
	*See instruction on Reverse Side	- TA MANINGER
	e ferri	AREA MANAGER