

NMCC

FARMINGTON DISTRICT

See Instructions on Reverse Side

JAN 26 1982

ACCEPTED FOR RECORD

APPROVED BY _____ DATE _____

(This space for Federal or State office use)

18. I hereby certify that the foregoing is true and correct
SUBSURFACE SAFETY VALUE: Manu. and Type _____ SET @ _____ FT.SIGNED *D. J. D. Brown* TITLE Drilling Clerk DATE January 25, 198218. I hereby certify that the foregoing is true and correct
SUBSURFACE SAFETY VALUE: Manu. and Type _____ SET @ _____ FT.

at 3659'. Cemented w/ 59cf. cement, for squeeze #4.

-10-82: Isolated casing leak w/ RTTS between 3770' and 3816'. Set cement retainer

-9-82: Taged cement at 3700' & drilled out to 4000'. Circ. hole.

up on casing to 1700 psi - squeeze #3. WOC.

ended to 3978'. Spot 49 cf. cement plug across bad casing, pressure

squeezed to 1500#, bled off to 750#. TH w/ tubing open

squeezed. Cemented w/ 118 cf. cement for squeeze #2. Cleamed out to below

cement for squeeze #1. Pressure tested to 1500#, did not hold.

Ran 4 1/2" casing failure 3915' to 3560' w/ 4 1/2" RTTS Packer.

-8-82: Pressured tested to 1500#, bled off to 750#. TH w/ tubing open

squeezed. Cemented w/ 118 cf. cement for squeeze #2. Cleamed out to below

cement for squeeze #1. Pressure tested to 3359'. Cemented w/ 236 cf.

Ran 4 1/2" casing failure set at 3359'. W/ 4 1/2" RTTS Packer.

-5-82: Pressured tested to 1500#, bled off to 750#. TH w/ tubing open

squeezed. Cemented w/ 118 cf. cement for squeeze #2. Cleamed out to below

cement for squeeze #1. Pressure tested to 1500#, did not hold.

Ran 4 1/2" casing failure 3915' to 3560' w/ 4 1/2" RTTS Packer.

-4-82: Pressured tested to 1500#, bled off to 750#. TH w/ tubing open

measured and true vertical depths for all markers and zones pertinent to this work.*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS GIVING DETAILS OF ALL PERMANENT DETAILS, AND GIVE PERIODIC DETAILS,

INCLUDING ESTIMATED DATE OF STARTING ANY PROPOSED WORK, IF WELL IS DIRECTLY DRILLED, GIVE SUBSURFACE LOCATIONS AND

TEST WATER SHUT-OFF SUBSEQUENT REPORT OF:RECEIVED *D. J. D. Brown* JAN 30 1982

(NOTE: Report results of multiple completion or zone

REPAIR WELL PULL OR ALTER CASING MULTIPLE ZONES CHANGE ON FORM 9-330)SHOT OR ACIDIZE PULL OR ALTER CASING MULTIPLE ZONES CHANGE ON FORM 9-330)FRACTURE TREAT TEST WATER SHUT-OFF SUBSEQUENT REPORT OF:REPORT, OR OTHER DATA 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,AT TOP PROD. INTERVAL: AT TOTAL DEPTH: AT SURFACE: 1090-N, 1850-W below,)

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. SEE SPACE 17) AREA SEC. 1, T-30-N, R-14-W

11. SEC. T, R, M, OR BLK. AND SURVEY OR 3. ADDRESS OF OPERATOR P.). Box 289, Farmington, NM 8740110. FIELD OR WILDCAT NAME EI PASO Natural Gas Company9. WELL NO. 2 1. OIL GAS WELL other8. FARM OR LEASE NAME Little Federal (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)7. UNIT AGREEMENT NAME 6. IF INDIAN, ALLOTTEE OR TRIBE NAME5. LEASE NM 28760 DEPARTMENT OF THE INTERIORUNITED STATES GEOLOGICAL SURVEYBUDGET BUREAU NO. 42-R1424 FORM APPROVED.

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices.

In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents nor sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

- 1-11-82: Drilled cement from 3519' to 3817'. Retainer was at 3659'. Pressure tested. Held 1500#, OK.
- 1-12-81: Blew well w/ gas to 3900'. Set 4 1/2 " RTTS packer @ 3508'. Isolated leak between 3770' and 3783'. TOOH w/ packer. Set cement retainer at 3659'. Cemented w/ 59 cf. cement for squeeze #5. *Drilled out cement.*
- 1-14-82: Pressure tested to 1000 psi, held ok. TIH w/ 3 7/8" mill on 2 3/8" tubing blowing down w/ gas.
- 1-15-82: Drilled Cmt. Retainer @ 6200'. Cleaned out w/ gas to 6435'. Ran 206 joints of 2 3/8", 4.7#, tbg. set at 3256'. Baker Model R production packer set at 4012'. Ret urned well to production.