

Submit 3 Copies
to Approprate
Director's Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Aramis, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-045-22344
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	E-6714 * LG-3016
7. Lease Name or Unit Agreement Name	STATE COM
8. Well No.	45
9. Pool name or Wildcat	TWIN MOUNDS FRUITLAND-PC
10. Elevation (Show whether DP, RKB, RT, GR, etc.)	GL 5415

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
CONOCO INC.

3. Address of Operator
10 Desta Drive STE 100W, Midland, TX 79705


4. Well Location
Unit Lease I : 1850 Feet From The SOUTH Line and 1190 Feet From The EAST Line
Section 32 Township 30 N Range 14 W NMPM SAN JUAN County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-11-93 MIRU. POOH W/ PRODUCTION EQUIP. GIH W/ TBG TO 919', PUMP 25 SX CLASS 'B' CMT FROM 919 TO 500', TAG CMT AND TEST CSG TO 500#, HELD. PUMP 30 SX CLASS 'B' CMT FROM 500' TO SURFACE, POOH. REMOVE SURFACE PRODUCTION EQUIPMENT, CUT OFF WELL HEAD AND ANCHORS BELOW GROUND LEVEL. INSTALL P&A MARKER.
2-13-93 RDMO, WELL P&A.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill R. Keathly TITLE SR REGULATORY SPEC. DATE 3-16-93
 TYPE OR PRINT NAME BILL R. KEATHLY TELEPHONE NO. 915-686-5424

(This space for State Use)

APPROVED BY Ernie Busch TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE JUL 0 1 1993
 CONDITIONS OF APPROVAL, IF ANY: