



**NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178 Fax (505) 334-6170

**GARY E. JOHNSON**  
GOVERNOR

**JENNIFER A. SALISBURY**  
CABINET SECRETARY

February 25, 1997

Ms Paula Mize  
Amoco Production Co  
SJ Oper Ctr 200 S Amoco Crt  
Farmington NM 87401

RE: Mansfield #1A A-19-30N-09W 30-045-22026  
Gartner A #4A I-33-30N-08W 30-045-22418

Dear Ms Mize:

According to our phone conversation on Tuesday, February 25, 1997 at 9:00 A.M., I am sending you back the Packer Leakage Tests on the above referenced wells.

The Mansfield #1A shows a pressure drop on the shut-in zone for day six of the test.


The Gartner A #4A doesn't indicate which zone was flowed for the test and it shows pressure drops for both zones on day six of the test.

Your options are as follows:

1. Reschedule well for retesting and contact our office at least 48 hours in advance so that we may provide a witness for the retesting.
2. After reviewing the Packer Leakage Test you feel that the well has a leakage problem, file notice of intent with the appropriate agency of what remedial work Amoco intends to do on these wells to bring them into compliance. Plans and work need to be done on or before February 25, 1998.

Please feel free to contact me at 334-6178 if you have any questions.

Sincerely,

  
Ernest Cardona  
Deputy O&G Inspector

EC/sh

attachments (2)

xc: well files  
EC file