

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

## Sundry Notices and Reports on Wells

## 1. Type of Well

GAS

## 2. Name of Operator

**BURLINGTON  
RESOURCES**

OIL &amp; GAS COMPANY

## 3. Address &amp; Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

## 4. Location of Well, Footage, Sec., T, R, M

1500' FSL, 1050' FEL, Sec.15, T-31-N, R-9-W, NMPM

## Lease Number

SF-078386

If Indian, All. or  
Tribe Name

## Unit Agreement Name

San Juan 32-9 Unit

## Well Name &amp; Number

San Juan 32-9 U #6A

## 9. API Well No.

30-045-22894

## 10. Field and Pool

Blanco Mesaverde

## 11. County and State

San Juan Co, NM

## 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

## Type of Submission

## Type of Action

<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other	

## 13. Describe Proposed or Completed Operations

2-10-99 MIRU. ND WH. NU BOP. SDON.  
 2-11-99 TIH w/fishing tools to fish rods & tbg. SDON.  
 2-12-99 Continue fishing. SD for wknd.  
 2-15-99 TOOH w/fishing tools. TIH w/chemical cutter, cut tbg @ 1872'. TOOH w/cutter. TIH w/fishing tools to fish, engaged fish. Continue fishing operations.  
 2-16/25-99 Continue fishing operations.  
 2-26-99 Recovered rods. TOOH w/rods. TIH w/fishing tools. SD for wknd.  
 3-1-99 TIH, tag top of fish @ 2812'. Pipe stuck. TOOH. TIH w/wireline. Ran freepoint, chemical cut tbg @ 5934'. TOOH w/wireline. Pipe still stuck. TIH w/chemical cutter, cut tbg @ 3569'. TOOH w/wireline. SDON.  
 3-2-99 TIH, engage fish. Recovered & TOOH w/2 3/8" tbg, some junk left in hole. TIH w/magnet, tag junk @ 3200'. TOOH, no recovery. TIH w/spear to top of lnr @ 3612'. Work dwn inside lnr to 3616'.  
 3-3-99 TOOH w/spear. TIH. SDON.  
 3-4-99 TIH, tag junk @ 3735'. Est circ, rotate through junk. Rotate through hole to 5962'. Circ hole clean. TOOH to above lnr top. SDON.  
 3-5-99 TIH, tag up @ 5828'. Est circ. Rotate & wash @ 5828-5920'. Circ hole clean. TOOH. TIH to 3552'. SD for wknd.  
 3-8-99 Unload well. Wash over to 5926'. TOOH. TIH to 3608'. SDON.  
 3-9-99 TIH, tag up @ 5746'. Circ. Wash down to 5926', top of fish. Circ hole clean. TOOH. SDON.  
 3-10-99 TIH w/188 jts 2 3/8" 4.7# J-55 tbg, set @ 5859'. ND BOP. NU WH. TIH w/one 2" x 1 1/4" x 10' x 14' Rhac-Z pump & rods. RD. Rig released.

## 14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 3/24/99

vkh

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

CONDITION OF APPROVAL, if any: