

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 0607

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Atlantic C

9. WELL NO.

6A

10. FIELD AND POOL, OR WILDCAT

Blanco PC/Blanco MV

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 6, T-30-N, R-10-W

N.M.P.M.

12. COUNTY OR PARISH 13. STATE

San Juan NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

El Paso Natural Gas Company

3. ADDRESS OF OPERATOR

Post Office Box 4289, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)

At surface

1105'N, 810'W

RECEIVED

14. PERMIT NO.

FEB 26 1986

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6034'GL

MAR 13 1986  
OIL CON. DIV.  
DIST. 3

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

02-01-86 MORU. Pulled 1 1/4" tbg. Attempted to pull 2 3/8" tbg.  
Tbg. stuck. Cut tbg. off at 2774'.  
02-02-86 Attempted to fish seal assembly.  
02-09-86 Finally recovered seal assembly. Now attempting to recover  
remaining tbg.  
02-11-86 Recovered remainder of 2 3/8" tbg. Ran 3 7/8" mill to  
PBTD.  
02-12-86 Set BP @ 4792'. Tested BP, ok. Set cement retainer @  
4554'. Squeeze cemented Menefee perforations with 50 sks.  
Class "B" with 1% TIC (59 cu.ft.) Set cement retainer at  
4114'. Squeeze cemented Cliff House perforations with 200  
sks. Class "B" with 2% calcium chloride and 1% TIC (236  
cu.ft.). WOC 18 hours.  
02-13-86 Cleaned out to 4554'. Ran packer and tested perms to 1000  
psi, ok. TOOH.  
02-14-86 Cleaned out to 4780'. Ran packer and tested perms to 600  
psi, ok. Cleaned out to PBTD.  
02-15-86 Set Baker packer @ 2791'. Ran 170 jts. 2 3/8" 4.7, J-55  
tbg., 5294' set @ 5306'. Seal assembly set in packer @  
2791'.  
02-16-86 Ran 85 jts. 1 1/4", 2.3#, J-55 tbg. 2764' set @ 2776'.

18. I hereby certify that the foregoing is true and correct

SIGNED

Drilling Clerk

02-25-86

TITLE

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD  
DATE

MAR 07 1986

\*See Instructions on Reverse Side

NMOCC

FARMINGTON RESOURCE AREA

BY