



DEVIATION TABULATION

Twin Mounds #1-E
Basin Dakota Field
San Juan County, New Mexico
Sec. 25, T30N, R14W

<u>Depth</u>	<u>Deviation</u>
760'	$\frac{1}{4}^{\circ}$
1260'	$\frac{1}{4}^{\circ}$
1760'	$\frac{3}{4}^{\circ}$
2262'	$\frac{3}{4}^{\circ}$
3265'	$\frac{3}{4}^{\circ}$
3775'	$1\frac{1}{4}^{\circ}$
4275'	$1\frac{1}{4}^{\circ}$
4725'	$1\frac{1}{4}^{\circ}$
5814'	$3\frac{1}{2}^{\circ}$
6065'	2°

I certify that this information is true and correct to the best of my knowledge.

Michael J. Wendling

Harlyn J. Walker
5/16/80

