Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED

BUREAU OF LAND MANAGEMENT		Expires: March 31, 1993
SUNDRY NOTICES AND DEPOSIT		5. Lease Designation and Serial No.
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		SF - 078996 b. If Indian, Allottee or Tribe Name
Use "APPLICATION FO	R PERMIT - " for such proposals 1 0 1983	The Name
	Tall the state of	
SUBMIT IN TRIPLICATE 1. Type of Well		7. If Unit or CA, Agreement Designation
Oil X Gas Well Other		San Juan 32-7 Unit
2. Name of Operator	Protes &	8. Well Name and No.
Phillips Petroleum Company 3. Address and Telephone No.		SJ 32-7 Unit #53
5525 Highway 64 NRU 3004 Farmington Aug 07-14		9. API Well No.
the Godage, Sec., 1., R., M., or Survey Description)		30-045-24164 10. Field and Pool, or exploratory Area
Unit P. 660' FSL & 1070' FEL		Los Pinos Ft.
Section 4, T31N, R7W		Sands Pictured Cliffs South
OUTO		11. County or Parish, State
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	San Juan, NM
TYPE OF SUBMISSION	T .	
Notice of Intent	TYPE OF ACTIO	N O 3 D
ED .	Abandonment	Charge of Plans
X Subsequent Report	Recompletion	New Construction
Final Abandonment Notice	Plugging Back Casing Repair	Non-Routine Frequering
I mai Apandonment Notice	Altering Casing	Water Strit-Off
	X Other Add pay & stimulate	Conversion to Injection
B. Describe Proposed or Completed C		
give subsurface locations and measured and true vertice	pertinent details, and give pertinent dates, including estimated date of state all depths for all markers and zones pertinent to this work.)*	Completion or Recompletion Report and Log form.)
ND Flowlines. Changed out master va	lvo. Dil ocilata i	
ND Flowlines. Changed out master valve. RU coiled tubing unit. PT OK. GIH w/coiled tubing. Tagged ice plug at 7'. Cleaned out plug. Cleaned out to PBTD @ 3733'. COOH w/coiled tubing. RU Blue Jet .		
NU w/packoff assembly. Perforated Lo	Dwer Pictured Cliffs @ 1 spf as follows:	d tubing. RU Blue Jet .
3556', 3554, 3548', 3548'	3595', 3583', 3578', 3572', 3567', 3558'	
- , 55 15	3342, 3494 , 3485 1/ Total holes (15 o	ld holes)
KU to stimulate PC Dumped 20 bb3. c	10, 403	
and ballsealers. Then pumped 60 Qual	% KCI water and 15 ballsealers, followed b tiy N2 foam frac. Frac'd lower PC with 47, 300 psi, ATR-20 bpm, ISDP 1700 psi, Flowe	y 250 gallons 15% HCL acid
TO SEE SEE SEE SEE SEE SEE SEE SEE SEE SE	200 n== 4TD 00	/40 # /U/40 Brady cand in
43,918 gal 60 Quality N2 foam. ATP-3300 psi, ATR-20 bpm, ISDP 1700 psi. Flowed back immediately on 2" hours. Turned well over to production.		
varied werr over to product 10	n.	a Flowed back on for 1/
1. I hereby certify that the foregoing is true and correct Signed		
THE WAY TO	Title Regulatory Assistant	
(This space for Federal or State office use)		Date3-2-99
Approved by	Title	
er e	Af	CEPTED FOR RECORD
tle 18 U.S.C. Section 1001		
representations as to any matter within its jurisdiction.	vingly and willfully to make to any department or agency of the United	States arMAD Qui.D. 4CQQ
		MAH, Undis Typidulent statements

* See Instruction on Reverse Side FARMUS BY_ NMOCD