30-045-24366 by division

	be seemed for	priPoser 1		•			P110 201	? Rev		
	packer les	hana testa	ORTHWEST NEV	W MEXICO PA	ACKER-L	EAKAG	E TEST			
Operator Location	<u></u>	whagh	Busource	Lease (	Quiar	rd		No. 1A		
of Well: U	Unit	Sec. <u>08</u> T	wp. <u>03/N</u>	Rge	008	W	Coun	y An lea	<u>'n / </u>	
	NAME OF RESERVOIR OR POOL			TYPE OF PROD. (Oil or Goe)		METHOD OF PROD. (Flow or Art. Lift)			MEDIUM or Cog.)	
Upper Completion	· Mesaclerde			gas		low		10	9	
Lower Completion				905 ( ) (bu)			I lon)	The		
			PRE-FLOV	SHUT-IN PI	RESSURE	DATA			/	
Upper Completion					81 press. pelg		ľ	Stabilized? (Yes or No.)		
Lower	Lower Hour, date shut-in		Length of time shul-in		SI prees, paig			Stabilized? (Yes or No)		
		<del>,                                    </del>		FLOW TEST	NO. 1					
Consmenced	at (hour, dat	o) #			Zone pr	educing (Upp	er or Lawerk			
TIN (hour,		LAPSED TIME SINCE*	PRESSU Upper Completion	Lower Completion		. ZONE MP.		REMARKS		
9141	02		1.40	0	ļ		Sakota La	as brief Pl	(g )	
			i l		798			7. T.A. as of 12/1/99		
	. <del></del>				1		7987.	13.7. as a	> 1//99	
							7987.	1917: AS 0	7 11199	
							7987.	1811: As O	Z 17/77.	
							7987.	1997: AS 0	> 1//79.	
							7987.	1997: AS Q	> 1/1/79.	
Production	on rate d	uring test					7987.	1991. As of	> 1/1/79.	
		_	) based on	Bbls. ir		Hours		1. A.S. O. C.		
Oil:		ВОРГ	) based on				G		OR	
Oil:		ВОРГ	MCFP	D; Tested thru	(Orifice	or Meter	G		OR	
Oil:		BOPE	MCFP	D; Tested thru	(Orifice	or Meter	G		OR	
Oil:	Hour, date s	BOPE	MCFP	D; Tested thru T SHUT-IN P	(Orifice	or Meter	G		OR	

ommenced at thour, dat	ie) + +		Zone preducing (Upper e	Lower:				
TIME (hour, date)	LAPSED TIME SINCE ##	PRESSURE		PROD. ZONE				
		Upper Completion	Lower Completion	TEMP.	REMARKS			
·								
<del></del>								
roduction rate d	uring test		<del></del>					
Oil:	BOPI	D based on	Bbls. in	Hours	Grav GOR			

nereby certify that the intormation	herein contained is true at	nd complete to the	best of	my knowledge
4 11000000	_		7	1 minutes

Approved AUG & 0 2002

New Mexico Oil Conservation Division

ORIGINAL SHOWED BY PROPERTY OF THE PERFE

Ву								
Title	<b>MARKET</b>	徼	*	#AS	INSPECTAGE.	PHIT.	N.E.	

Operator

Crator Burling to

the state of

Tide Jease Toppater

Date 8/14/02

## NORTHWEST NEW MEDICO PACKER LEAKAGE TEST INSTRUCTIONS

- A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the rubing have been distracted. Tests shall also be taken at any time that communication is suspected or when requested by the Division.
- At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Division in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- 3. The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains short-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial packer leakage test, a gas well is being flowed to the atmosphere due to the lack of a pipeline connection the flow period shall be three hours.
- 5. Following completion of Flow Test No. 8, the well shall again be shot-in, in accordance with Paragraph 3 above.
- 6. Flow Test No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test No. 2 is to be the same as for Flow Test No. 1 except

- that the previously produced some shall remain shut-in while the some which was previously shut-in is produced.
- 7. Pressures for gus-come cests must be measured on each zone with a deadweight pressure gauge at time intervals as follows: 3 hours tests: immediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour theroof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the conclusion of each flow period. 7-day term: immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test data.

24-hour oil zone rests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.

8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aster District Office of the New Mexico Oil Conservation Division on Northwest New Mexico Packer Leakage Test Form Revised 10-01-78 with all deadweight pressures indicated thereon as well as the flowing temperatures (gas sones only) and gravity and GOR (oil zones only).