UNITED STATES

FORM APPROVED u No. 1004-0135 larch 31, 1993

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT	Budget Bureau No. Expires: March 3
SUNDRY NOTICES AND REPORTS ON WELLS	5. Lease Designation and Serial No.

	sals to drill or to deepen or reentry to a different reservoir.		10989
Use "APPLICA"	FION FOR PERMIT - " for such proposals	6. If Indian, Allottee or Tribe	Name
		7. If Unit or CA, Agreement	Designation
1. Type of Well			
Oil Gas Other		8. Well Name and No.	110
2. Name of Operator	Attention:	FIELDS	4R 73
AMOCO PRODUCTION COMPA	NY Julie Acevedo	9. API Well No.	
3. Address and Telephone No. P.O. Box 800, Denver, Colorado	80201 (303) 830-60033	3004!	524501
4. Location of Well (Footage, Sec., T., R., M., or Su			averde
1270'FNL 1270'FW	Sec. 28 T 32N R 11W NW/NW	11. County or Parish, State SAN JUAN	NEW MEXICO
12. CHECK APPROPRIA	TE BOX(s) TO INDICATE NATURE OF NOTICE, R	EPORT, OR OTHER	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION	**************************************	
Notice of Intent Subsequent Report	Abandonment Recompletion Plugging Back Casing Repair Altering Casing	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection	
Final Abandonment Notice	Other Perf and Frac (Note: Report Recompletion	Dispose Water rt results of multiple completion in Report and Log form.)	n on Well Completion or
Please see attached for proce	DECEIVE JUNI 0 1993 OIL CON. DIN	070 FARMINGTON, NM	RECEIVED BLM 93 JUN -4 AM 9: 59
14. I hereby certify that the foregoing is true and cor	Cr Staff Agai	staat	03-30-1993
Signed Julia Will	Title Sr. Staff Assi		
(This space for Federal or State office use)	Title		FOR RECORD
Approved by Conditions of approval, if any:			8 1993
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, notice of the United States and the Unite			

MIRUSU 3/5/93, NDWH, NUBOPS. TOH W/ 237 jts TBG. TIH W/CIBP & set @ 7400'. Press test to 2500psi. Held OK. TOH W/TBG. ND BOPS and WH, installed 5000# WH press. test to 3500psi. seal leaked. Removed WH. RU WLE. RIH and dumped bailed cmt on CIBP set @ 7410'. CMT TOP @ 7347'. Installed new WH & frac valve & press. test CSG & WH to 3500psi. Held. RU WLE & RIH ran CBL, CCl, GR from 5717' to surf CMT top on 4.5" CSG @ 3800', CMT top 7" CSG @ 3000'. RIH and Perf CSG.

Perf: 5476'-5480', 5536'-5540', 5553'-5556', 5558'-5560', 5574'-5576', 5596'-5599, 5616'-5620', 5654'-5658', W/1 JSPF .48" diam.

RIH & set RET RBP @ 5465'. RIH & dumped 5' of sand on RBP. RIH and perf MV Point lookout from 5434'-5442', 5414'-5416, 5367'-5404', 5338'-5354', W/2 JSPF, .48" diam..

Frac: interval 5442'-5338' W/ 190,000 GAL BORAGEL, 177500# 12/20 Brady sand, AIP 637psi. AIR 80 BPM. total 190,000gal.

RIH & set RBP @ 5015'. press. test RBP to 2000psi. Held OK. RIH & dumped 5' sand on RBP.

RIH and perf MV. Cliff house interval 4942'-4961', 4927'-4039', 4921'-4923', 4915'-4918', 4898'-4911', 4886'-4892', 4810'-4831, W/2 JSPF, .48" diam. RD WLE

RU Frac equip. frac Cliff house perfs from 4810' to 4961' W/59693 gal gel pad & 36334 gal-gel with 1190sxs 119000lbs of 12/20 brady sand. screened out on 4.28 LBS/GAL. AIP 1100psi. AIR 85 BPM. Displaced Frac W/3246 GALS total load to recover =2363 BBls. RD.

TIH W/RET. head & tagged sand @ 3610'. Rel. RBP @ 5465'. Plug would go down but would not come up worked for 4.5hrs. Tied to circ hole W/N2- did not get any N2 back to surf- pump 75000 SCF- RBP came free & TOH W/plug. TIH W/ new RET head to liner. TIH W/RET. head for RBP set @ 5465' tagged fill @ 5390'. RU N2 equip. & cleaned out sand W/ 150,000 SCF of N2. REL. RBP & TOH. RIH & set RBP @ 4775' Press. test RBP to 2000psi. held OK. RIH & dumped 5' sand on RBP set @ 4775'.

RIH and perf MV from 4720'-4725', 4712'-4717, 4685'-4688', 4671'-4673', 4664'-4666', 4574'-4590', with 2 JSPF, .48' diam.

Frac: MV intervals 4725'-4574' by pumping 30,000 GAL X-link GEL & stagging in 1435sx of 12/20 Brady sand up to 7 LBS per gal, AIP 624psi. AIR 40 BPM.

TIH W/ bit & scrapper to liner top @ 3436'- TIH W/RBP & set @ 3400'. RU Wle & RIH dumped 5' of sand on RBP. RIH & perf CSG @ 2958' W/2 JSPF, .5" diam. RIH & set CMT RET. @ 2720'. TIH & stung into ret @ 2720'. Mixed & pumped 50 sx Cl B CMT & 200sxs of 35/65 poz & tailed in W/ 100sxs of CL B . stung out of ret with 350psi., dump 1/2 BBls CMT on RET. & TOH W/ stinger. RIH & perf CSG @ 1576' W/ 2 JSPF .48" diam. TIH W/RET. PKR & set @ 1262' press test PKR to 500psi OK. est. inj. rate 2 1/2 BPM @ 900psi. W/45 BBls- no circ on BH. RU cmt equip. mixed & pumped 50sx Cl B cmt followed by 150sx of 65/35 poz & tailed in W/100sx CL B, W/60 BBls pumped the BH started to circ to surf, W/ partial returns. lost returns W/70 BBls pumped, displaced CMT to 1470', reversed out no cmt . REL PKR & TIH W/bit & scrapper & tagged up @ 1288' and drilled up CMT to 1585'- press. test squeeze holes @ 1576' to 500psi. Held OK. TIH & tagged cmt on CMT RET. @ 2700' Drilled CMT & CMT RET @ 2720' & drilled cmt to 2980', Circ hole clean, Press. test to 500psi. Held OK. TOH. RU WLE & ran CBL from 3300' to Surf. CMT top @ 500'. Released RBP set @ 3400' & TOH. TIH W/RET HEAD for RBP set @ 4775' RU N2 equip. and circ sand off of RBP with 70000 SCF N2. Rel. RBP & TOH, TIH W/2 3/8" TBG & landed @ 5383'. ND BOPS NU WELL Head 3/20/93.