

HALLIBURTON SERVICE JOB 100


CHART NO.	TIME	IN	OUT	PSI	TEMP	REMARKS
	0700					arrived at site
1	0700	12	320	0		Load Tubing
2	0909	12		0		start injecting
3	0948	12	89	100		Pressure & Rate
4	0953	12	147	180		Signal
5	0953	15		220		Start 1/2 Day
6	0932	15		410		Pressure & Rate
7	0938	16	390	430		Signal
8	0938	16		450		Increase Rate
9	0945	16	368	480		Pressure & Rate
10	0953	16		510		Signal
11	1000	1		610		Increase Rate
12	1000	1		640		Pressure & Rate
13	1007	1		660		Signal
14	1007	1 1/2		730		Increase Rate
15	1015	1.5		770		Pressure & Rate
16	1021	1.5		810		Signal
17	1021	2	1103	850		Increase Rate
18	1028	2		920		Pressure & Rate
19	1030	2		950		Signal
20	1039	3		1080		Increase Rate
21	1041	3		1100		Pressure & Rate
22	1047	3		1165		Signal
23	1047	4		1390		Increase Rate
24	1051	4		1450		Pressure & Rate
25	1050	4		1500		Signal
26	1101	5		1700		Increase Rate
27	1107	5		1710		Pressure & Rate
28	1113	5		1770		Signal
29	1115	6		2110		Increase Rate
30	1122	6		2060		Pressure & Rate
31	1130	6		2150		Signal
				1000		Isip
				900		5 min
				820		10 min
				780		15 min
				730		20 min

RECEIVED


MAY 1 9 1968


OIL CON. DIV.
DIST. 3

Wick Madsen
Denver 206
11-88



3





5

8

8

7

6

