UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

	5. LEASE NM-03566			63000 6 A 31 184 93	
	6. IF INDIAN, AL	LOTTEE O	R TRIB	E NAME	
1-				<u> </u>	
١	7. UNIT AGREE	MENI NAM	1 L		
Γ	8. FARM OR LE		:	- 2: 3	
1	Gage Con	r Contract	į	수의료	
-	9. WELL NO. 1E				
-	10. FIELD OR WI	LDCAT NA		# 1 1 T	
-	Basin Da		 :	7 1:	
	11. SEC., T., R.,		K. AND	SURVEY	OR
1	AREA	本表 billion	Ş	# = * i	
L	Sec. 20				
ı	12. COUNTY OR				<u>:</u>
L	San Juar	ا تو	New	Mexico	<u> </u>
-	14. API NO.	3 _ =	Ξ	1 miles	
-	45 51514710416		- KO	D 4ND	
	15. ELEVATIONS	2.4 ·	JF, KU	B, AND	yνυ)
L	6226 ' gi		- 1		
 44		18 10 10 10 10 10 10 10 10 10 10 10 10 10	M		(1)
	VEL	- 4		~~~	
	(NOTE: Report re change o	sults of in alt	ipl e\}	Happy or	1982
	Change	1 101111 3	ÖIĒ	CON.	MOS
	AL SURVEY	_ = : _ = = ¹	٠. ١	DIST	
	v, N. M.	- 3 1 - 2		e e e e e e e e e e e e e e e e e e e	
		9740			<u>.</u>
ite	all pertinent det	ails, and g	give pe urface	rtinent d	ates,
ent	to this work.)*		**		
og	. & 3-7/8" I	oit. D	rld.	to PB'	DI BO
W	tr. Spotte	i buu g	al.		
		: FB : 1	·		<u>.</u>

Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)							
1	oil		gas				

SUNDRY NOTICES AND REPORTS ON WELLS

well <u>K</u>X other 2. NAME OF OPERATOR Tenneco Oil Company 3. ADDRESS OF OPERATOR P.O. Box 3249, Englewood, CO 80155 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 810' FSL, 790' FEL

AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE **CHANGE ZONES** ABANDON*

(other)

AT TOP PROD. INTERVAL:

SUBSEQUENT REPORT OF:

U. S. GLUL⁽⁾⁽ FARMINGT

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine

2/11/82 - MIRUSU, NDWH, NUBOP, talleyed & RIH w/th L 7300'. PT csg. to 3500 psi. Circ. hole w/l% KCL across perfs. POOH w/bit & tbg.

2/12/82 - Ran GR/CCL. Perf'd Dakota w/3-1/8 csg. gun & 2 JSPF fr. 7121-30' & w/1 JSPF fr. 7203-22' (28 holes, 37'). Brk down formation @ 1800 psi. Acidized & balled off w/700 gal. 15% wtd HCL & 56 1.1 SG ball slrs. Ball off complete. Frac'd Dakota w/50,000 gal. 75% foam & 93,000 20/40 sd. Left flwg.

2/13/82 - RIH w/tbg. SN & pump out plug. Tagged sd fill @ 7265'. Approx 20' of sd. CO to PBTD w/foam. Killed well and landed tbg. @ 7150'. NDBOP, NUWH, well came around natural. RDMOSU. 2/14/82 - Flwg. to CU.

Subsurface Safety Valve: Manu. and Type ___

18. I hereby ceptify that the foregoing is true and correct _ TITLE Production Analyst DATE _ <u>2/26/82</u>

(This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

MAR 05-1982

Set @