

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT - " for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM-03402
2. Name of Operator Phillips Petroleum Company	6. If Indian, Allottee or Tribe Name
3. Address and Telephone No. 5525 Highway 64, NBU 3004, Farmington, NM 87401 505-599-3454	7. If Unit or CA, Agreement Designation San Juan 32-8 Unit
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit P, 1150' FSL & 810' FEL Section 22, T-31-N, R-8-W	8. Well Name and No. SJ 32-8 Unit #8A
	9. API Well No. 30-045-25126
	10. Field and Pool, or exploratory Area Blanco Mesaverde
	11. County or Parish, State San Juan, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other <u>Reperforate Zone</u>
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

POOH with 2-3/8" tubing. Clean out wellbore. Reperforate Mesaverde from 5312'-5762'.
Perforate Lewis Shale from 4350' - 4951' OA. Breakdown each interval w/PIP tool & 15% HCl.
Flowback to clean up. Run spinner survey. Rerun 2-3/8" production tubing.

14. I hereby certify that the foregoing is true and correct

Signed E. Haseby Title Envir./Regulatory Engineer Date 2-27-95

(This space for Federal or State office use)

Approved by _____ Title _____
Conditions of approval, if any: _____

APPROVED

MAR 06 1995

DISTRICT MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

* See Instruction on Reverse Side

NM000