

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

NM 048576

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Foothills NO. 2

9. API Well No.

30-045-25546

10. Field and Pool, or Exploratory Area

Picture Cliffs - Fulkner Kutz

11. County or Parish, State

San Juan County, New Mexico

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

TEXAKOMA Oil and Gas Corporation

214/701-9106

3. Address and Telephone No.

ONE LINCOLN CENTRE, 5400 LBJ FRWY, Ste 500, Dallas, Texas 75240

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec. 19, T 30N, R 12W

1080' 7NL and 1080' 7WL

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Propose to plug and abandon well by filling 2 7/8", 6.5 spf, casing with 60 sacks of cement from PBTD (1,979') to surface, cement - neat with 4% gel. Perforations @ 1971' - 1979' (8'). Bottom of surface casing @ 100' (7" 20ppf), surface casing is cemented to surface. Cut 7" and 2 7/8" @ surface, weld on cap. Install Dry Hole Marker, Restore Location if necessary. (with proper well identification)

Top of Fruitland Formation - 1600'
Top of Picture Cliffs - 1966'
ELEVATION - 5874' GR

14. I hereby certify that the foregoing is true and correct

Signed Walter J. Toups Jr.
(This space for Federal or State office use)

Title Drilling MANAGER

Date MARCH 28, 1996

Approved by _____
Conditions of approval, if any:

Title _____

NMOCD

APPROVED

APR 02 1996

