

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other

2. NAME OF OPERATOR
Robert L. Bayless

3. ADDRESS OF OPERATOR
P.O. Box 1541, Farmington, NM 87499

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1810' FSL & 1100' FEL
AT TOP PROD. INTERVAL: same
AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) T.D. well

SUBSEQUENT REPORT OF

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED
JUL 26 1983

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

(NOTIFY Report results of multiple completion or zone change on Form 9-330.)

RECEIVED

1983

ON. DIV.
3

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-20-83 Drilling @ 2429'

7-21-83 Drilling @ 3660'

7-22-83 Drilling @ 4700' with Benex water.

7-23-83 Drilling @ 5230'. Mud weight 9.0, viscosity 37, water loss 19.0

7-24-83 Drilling @ 5745'. Mud weight 9.0, viscosity 33, water loss 10.0

7-25-83 Drilling @ 6167'. Mud weight 9.0, viscosity 38, water loss 10.0

(continued on back)

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE Operator DATE July 26, 1983

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

AUG 0 8 1983

*See Instructions on Reverse Side

NMOCC

FARMINGTON RESOURCE AREA
FARMINGTON, NEW MEXICO

BY

[Signature]

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between, and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

GPC : 1981 0 - 347-166

(cont)

7-26-83 T.D. well at 4:00 p.m. 7-25-83. Condition hole. Tripped out of hole. Rigged up Gearhart. Induction log hit bridge at 1060'. Round trip pipe to 1572' to knock out bridge. Induction log stopped at bridge at 1510'. Tripped pipe in hole to 1634'. Raised viscosity of mud and circulated hole clean of debris. Tripped pipe out of hole. Induction log stopped at 1293'. Cleaning out hole to log.