

F

30-045-25767

7-7-83

F. Loc. 1570/S; 1750/W Elev. 5702 GL Spd. _____ Comp. _____ TD _____ PB _____

Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. I. _____ @ _____ Csg. Perf. _____ Prod. Stim. _____

T
R
A
N
SBO/D _____ Grav. _____ 1st Del. Gas _____
MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NITD X	Well Log	TEST DATA							Ref. No.
Ojo Alamo		C-103	Plot X	Schd.	PC	Q	PW	PD	D		
Kirtland		C-104	Electric Log								
Fruitland			C-122								
Pictured Cliffs		Ditr	Dfo								
Chacra		Datr	Dac								
Cliff House		Acres S320									
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											

P

o

o

I

Basin

Dakota

Co SJ

S 23

T 30N

R 14W

U K

Oper. Robert L. Bayless

Morton

No. 2E

Morton #2E

K-23-30N-14W

Robert L. Bayless

Caller Service 4104
Farmington, New Mexico 87499

CERTIFIED--RETURN RECEIPT REQUESTED

Robert L. Layless
P. O. Box 1541
Farmington, NM 87499

FEB 4 1985

Gentlemen:

Reference is made to your Applications for Permit to Drill (APDs) for the following wells:

1. No. 6 Jicarilla 363 B, SW/4NW/4 sec. 15, T. 24 N., R. 4 W., Rio Arriba County, New Mexico, lease Jicarilla Contract 362.
2. No. 2-E Morton, NE/4SW/4 sec. 23, T. 30 N., R. 14 W., San Juan County, New Mexico, lease NM-26357.
3. No. 2 Jicarilla 65 B, NW/4NE/4 sec. 16, T. 25 N., R. 4 W., Rio Arriba County, New Mexico, lease Jicarilla Contract 65.
4. No. 2 Jicarilla 118 B, SE/4SW/4 sec. 26, T. 26 N., R. 3 W., Rio Arriba County, New Mexico, lease Jicarilla Contract 118.
5. No. 3 Jicarilla 118 B, NW/4SE/4 sec. 26, T. 26 N., R. 3 W., Rio Arriba County, New Mexico, lease Jicarilla Contract 118.

As discussed with Lulu Berger of your Company on January 29, 1985, the subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely yours,


for Area Manager

Enclosures

cc:
BIA, Dulce
NMOCC

RECEIVED

FEB 05 1985

OIL CON. DIV.
DIST. 3

ABANDONED LOCATION