

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1500' FSL, 1190' FEL, Sec. 15, T-30-N, R-11-W, NMPM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent	☐ Abandonment	☐ Change of Plans
☒ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut off
	☐ Altering Casing	☐ Conversion to Injection
	☒ Other - Pay add	

13. Describe Proposed or Completed Operations

2-7-98 MIRU. ND WH. NU BOP. TOOH w/159 jts 2 3/8" tbg. TIH w/3 3/4" gauge ring to 4590'. TOOH. TIH w/4 1/2" CIBP, set @ 4570'. Load hole w/120 bbl 1% Kcl wtr. Ran CBL-CCL-GR @ 2494-4570', TOC @ 2494'. TOOH. PT csg to 800 psi, OK. TIH, spot 170 gal 15% Hcl @ 4472'. TOOH. TIH, perf Menefee w/1 SPF @ 4206, 4211, 4235, 4242, 4255, 4315, 4319, 4337, 4360, 4391, 4395, 4411, 4415, 4417, 4437, 4444, 4450, 4454'. TIH w/4 1/2" pkr, set @ 4498'. PT CIBP to 3000 psi, OK. Release pkr, TOOH. Acidize w/1500 gal 15% Hcl. TOOH.

2-8-98 Frac Menefee w/1296 bbl 30# linear gel, 90,000# 20/40 Arizona sd. CO after frac.

2-9-98 Blow well & CO. Drill out CIBP.

2-10-98 Blow well & CO to PBTD @ 5040'. TOOH. TIH, ran GR & after frac logs @ 4000-5033'. TOOH. TIH, blow well & CO. TOOH.

2-11-98 Blow well & CO. TOOH. TIH w/154 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 4791'. ND BOP. NU WH. RD. Rig released.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 3/17/98

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

CONDITION OF APPROVAL, if any:

Date 3/17/98 **RECEIVED FOR RECORD**

MAR 23 1998

FARMINGTON DISTRICT OFFICE

NMCCD