

Submit 3 Copies  
to Appropriate  
District Office

DISTRICT I  
P.O. BOX 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Box DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico  
Energy, Minerals and Natural Resources Department

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

Form C-103  
Revised 1-1-89

WELL API NO.

30-045-27479

5. INDICATE TYPE OF LEASE  
STATE ☒ FEE ☐

6. STATE OIL & GAS LEASE NO.

7. LEASE NAME OR UNIT AGREEMENT NAME

FC STATE COM

8. WELL NO.

1

9. POOL NAME OR WILDCAT

BASIN FRUITLAND COAL

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. TYPE OF WELL:  
OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR  
CONOCO INC.

3. ADDRESS OF OPERATOR  
10 DESTA DR., SUITE 100W, MIDLAND, TX 79705-4500

4. WELL LOCATION  
Unit Letter G : 2305' Feet From The NORTH Line and 1460' Feet From The EAST Line  
Section 32 Township 31N Range 08W NMPM SAN JUAN County

10. ELEVATION (Show whether DF, RKB, RT, Gr, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

#### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER: Install Rods ☒

12. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  
SEE RULE 1103.

7/9/97 MIRU. ND upper tree, RIH w/ 2" x 1 1/2" x 16' RHAC pump 2 - K bars, 121 3/4" rods, 2 - 2', 1 - 4', 1 - 6', 1  
8' pony rods, 16' polish rod, set pump & space out for 60" stroke length, NU stuffing box, RDMO.

RECEIVED  
JUL 15 1997  
OIL & GAS DIV.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Debra Bemenderfer

TITLE AGENT FOR CONOCO INC.

DATE 7/15/97

TYPE OR PRINT NAME: DEBRA BEMENDERFER

TELEPHONE NO.

(This space for State Use)

APPROVED BY

Johnny Robinson

TITLE

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE

JUL 15 1997

CONDITIONS OF APPROVAL, IF ANY:

**F. C. STATE COM #1**  
**A.P.I. 3 30-045-27479**  
**SEC. 32, T-31-N, R-08-W, UNIT LETTER "G"**  
**2305 FNL - 1460 FEL**  
**ATTACHMENT FOR OCD C-103**

5-28-97 MIRU, NU, CHOKE MANIFOLD BLOW LINES, PT 7" CSG & CIBP. ND, MU, NU, BOP'S, HCR VALVES. NU BLOOIE LINES, PT, STACK CM, HCR VALVES REPLACE 4-3/4" RAMS, REPAIR LEAKS, RETEST 250# LOW, HIGH 3000#. RU, AIR AND BLEED LINES. ND. PU DP- CIBP @ 2178', RU POWER SWIVEL. UNLOAD HOLE, DRIG CIBP. SWIVEL IN HOLE TAG @ 2818'. C/O F/2818' - 2863' W/ 3000 CFM AIR, 15 BPH MIST, SWIVEL WENT DOWN. PUIC, CIRC W/ AIR MIST. C/O F/2863' - 3156' W/ 3000 CFM AIR 15BPH MIST, RETG HVY COAL 1/4" FINES 5-7 BPH H2O. R&R @ 3156' W/ 1500 CFM 10-BPH MIST, RETG HVY-LT COAL FINES. TOO H W/ BIT. RU TO SURGE WELL. FLOWTEST 2-3/4" SIBU TEST. SURGE WELL F/SURFACE 14 TIMES 180 PSI RETG HEAVY-MED COAL FINES H2O AND GAS. SURGE WELL F/ SURFACE 16 TIMES RETG HVY-LT COAL FINES H2O. THE BUILD PRESSURE DROPPED F/ 190 PSI TO 160 PSI. TIH TAG @ 2833'. C/O BRIDGE F/2833', - 2848'. C/O FILL F/ 2940' - 3156', 216 FILL W/ 1500 CFM AIR, 10 BPH MIST, BOOTED UP OFF HOLE. PUH - 3032'. C/O F/ 3032' - 3156' W/ 2250 CFM AIR, 10 BPH MIST. R&R F/ 3125' - 3156' W/ 2250 CFM AIR, 10 BPH MIST, RETG HEAVY COAL FINES, 5-7 BPH H2O. R&R F/3125' - 3156' W/ 1500 CFM AIR, 10 BPH MIST, RETG MED/HVY COAL FINES, 5-7 BPH H2O GAS. R & R F/3125' - 3156' W/ 1500 CFM AIR, 10 BPH MIST, RETG MED/HVY COAL FINES, 7-10 BPH H2O, GAS. R & R F/3125' - 3156' W/ 750 CFM AIR, 10 BPH MIST, RETG HVY/LT COAL FINES, 7-10 BPH, H2O, GAS. TOO H W/BIT. FLOW TEST 2", 3/4" SIBU TEST, SURGE F/ SURFACE 14 TIMES @ 190 PSI RETG MED/HVY COAL FINES 1/16" FINE IN SIZE, H2O, GAS. SURGE WELL F/SURFACE W/ 3000 CFM AIR @ 230 PSI, COAL RETURNS & H2O DECREASED WITH AIR SURGE. SURGE F/ SURFACE 15 TIMES @ 190 PSI, RETG HVY COAL 1/4" FINES, H2O, GAS. SURGE WELL F/ SURFACE 15 TIMES @ 190 PSI, RETG HVY COAL 1/2" FINES. TIH W/BIT TAG @ 3066', C/O F/ 3066' - 3156' W/ 1500 CFM AIR, 10 BPH MIST, RTG HVY COAL 1/2" FINES, 7-10 BPH, H2O, GAS. R & R F/3125' - 3156' W/ 1500 CFM AIR, 5 BPH MIST, RETG HVY/MED COAL 1/4" FINES, 7-10 BPH, H2O, GAS. R & R F/3125' - 3156' W/ 750 CFM AIR, 5 BPH MIST, RETG HVY/MED COAL 1/4" FINES, 7-10 BPH, H2O, GAS. TOO H W/BIT. FLOW TEST 2", 3/4" SIBU TEST. SURGE WELL F/ SURFACE 13 TIMES @ 190 PSI, RETG HVY COAL FINES 1/4", H2O, GAS. SURGE WELL F/ SURFACE 16 TIMES @ 190 PSI, RETG HVY/LT. 1/4" COAL FINES, H2O, GAS. TIH W/BIT, TAG @ 3121'. COTB W/ 1500 CFM AIR, 10 BOH MIST. R & R F/3125' - 3156' W/1500 CFM AIR, 10 BPH MIST, RETG VERY HVY 1/4" COAL FINES, H2O, 7-10 BPH, GAS. R & R F/3125' - 3156' W/ 1500 CFM AIR, 10 BPH MIST, RETG. VERY HVY. 1/4" COAL FINES, 7-10 BPH, H2O, R & R F/3125' - 3156' W/ 1500 CFM AIR, 10 BPH MIST, RETG VERY MED/HVY 1/4" COAL FINES, 7-10 BPH, H2O, GAS. R & R 3125' - 3156' W/ 1500 CFM AIR, 10 BPH MIST, RETG MED/HVY 1/4" COAL FINES, 7-10 BPH, H2O, GAS. R & R F/3125' - 3156' W/ 750 CFM AIR, 5 BPH MIST, RETG LT/MED 1/4" COAL FINES, 7-10 BPH, H2O.

R & R F/3125' - 3156' W/ 750 CFM AIR NO MIST, RETG COAL FINES, 7 BPH, H2O. TOO H W/ BIT. FLOW TEST 2", 3/4" SIBU TEST, TIH, TAG @ 3128, COTB W/1500 CFM AIR, 5 BPH MIST, R & R F/ 3125' - 3156' W/ 1500 CFM AIR, 5 BPH MIST, RETG HVY/LT COAL FINES, PUIC FLOW WELL ON 7" BLOOIE LINES. CIH. TAG @ 3130' COTB. R & R W/1500 CFM AIR, 5 BPH MIST, RETG LT/HVY COAL FINES. PUIC FLOW WELL ON 7" BLOOIE LINES. CIH. TAG @ 3130' COTB. R & R W/1500 CFM AIR, 5 BPH MIST, RETG LT/HVY COAL FINES. GIH. TAG@ 3121' COTB. R & R W/ 1500 CFM AIR, 5 BPH MIST, RETG MED/LT COAL FINES. RU, MU & TIH W/ 6 1/4" BIT, BS W/ FLOAT 11 JTS 5 1/2" LINER, 5 1/2" X 7" LINER HANGER. SET LINER. RU, PERF F/ 3120' - 3102', 3044' - 3063', W/4" CSG GUN .61" HOLES @ 45 PF ON 2<sup>ND</sup> GUN RUN, GUN STUCK. HOOK UP T BAR. PULL ON LINE W/ BLOCKS. PULLE LOOSE. TOO H W/ GUN. FOUND GUN SWELLED - SHOT HOLES. PERF F.C. F/ 3000' - 3006', 2766' - 2975' GUN STUCK. HOOK UP T BAR, PULL ON LINE W/ BLOCKS. PULLED OUT. RIG DOWN.

W/O TRC & FISHING TOOLS. OFF LOAD TALLEY, RABBIT, PU, MU. REPAIR TUBING TONGS. PU, 2 3/8" TBG, TAG FISH @ 2963'. CHASE FISH TO BOTTOM. TOO H W/ FISH LD, TOOLS AND FISH. RU. PERF FC F/2926' - 2950' W/3 1/8 HSC GUN. .42 DIA. HOLES. RD.TIH W/2 3/8" FISHING STRING. LD SAME, LOAD OUT, TBG & DC'S. PU 2 3/8" CS. TBG. LOAD TBG @ 3115' W/ SAW TOOTH COLLAR, 2 3/8" JT, 1.78" SN, 1.875" X N 105 JTS TBG, SN, ND, BOP'S, NU 7" MASTER VALVE.

6-23-97 RIG DOWN.