

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-045-27643
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Quinoco Yager N
8. Well No. 5
9. Pool name or Wildcat Basin Fruitland Coal
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6,564' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Quinoco Petroleum, Inc.
3. Address of Operator P. O. Box 378111, Denver, CO 80237	4. Well Location Unit Letter <u>N</u> : <u>1160</u> Feet From The <u>South</u> Line and <u>2315</u> Feet From The <u>West</u> Line Section <u>3</u> Township <u>31N</u> Range <u>7W</u> NMPM <u>San Juan</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6,564' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

April 11, 1990

1. Drill to 367'. RU & run 8 jts (347.58') 9-5/8" 36# K-55 csg.
2. Cmt w/200 sxs class "B" w/2% CaCl₂.
3. Circ cmt to surf, bump & press plug to 1000# @ 3:30 PM.
4. WOC 8 hrs.

April 12, 1990.

5. Drill 8-3/4" hole from bottom of surf. pipe to 2166'.

April 13, 1990

6. Drill 8-3/4" hole to 3090' KB.
7. Circ hole, TOH & LD drill pipe & collars.
8. RU & run 7" 20# ST&C K-55 csg., landed @ 3090' KB.
9. Cmt w/500 sxs 65-35 light & 80 sxs class "B" w/2% CaCl. Displace w/125' BW.

(continue on back)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Holly S. Richardson TITLE Sr. Ops. Eng. Tech. DATE April 30, 1990
(303)
TYPE OR PRINT NAME Holly S. Richardson TELEPHONE NO. 850-6322

(This space for State Use)

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT III DATE MAY 02 1990

CONDITIONS OF APPROVAL, IF ANY:

9. continued

Bump & press plug 500 psi over circulating press. Plug down @ 10:05 PM.

10. Release rig @ 12:00 PM 4/13/90.

11. W.O.C.