

F

30-045-26922

5-19-88

F. Loc. 1840/S; 1460/W Elev. 6227 GL Spd. _____ Cu. ft. _____ Cu. ft. _____
 Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
 Csg. Perf. _____ Prod. Stim. _____

T Gas
R
A
N
S

BO/D _____ Grav. _____ 1st Del. Gas _____
 I.P. _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NITD ☒	Well Log	TEST DATA							Ref. No.
Ojo Alamo		C-103	Plat ☒	Schd.	PC	Q	PW	PD	D		
Kirtland		C-104	Electric Log								
Fruitland			C-122								
Pictured Cliffs		Ditr	Dfa								
Chacra		Datr	Dac								
Cliff House											
Menelee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
		Acres ^{h/320} 160									

R-8768

Basin Fr. Coal. Co. SJ S 34 T 31N R 8W U K Oper. Southland Royalty Co. Lse. Hale No. 351

Hale #351

K-34-31N-8W

SOUTHLAND ROYALTY CO.

SF-079073 et al. (WC)
3162.3-1(F) (019)

JAN 05 1990

Southland Royalty Company
P. O. Box 4239
Farmington, NM 87499

RECEIVED

JAN 10 1990

OIL CON. DIV.
DIST. 3

Gentlemen:

The following APDs are rescinded and returned due to drilling not having commenced prior to the expiration date of the APD extension as granted.

<u>APD Well No.</u>	<u>Expiration Date of Extension</u>
✓ 350 Hale, SW/4SW/4 sec. 27, T. 31 N., R. 8 W., lease SF-079037	11/16/89
✓ 351 Hale, NE/4SW/4 sec. 34, T. 31 N., R. 8 W., lease SF-079037	11/16/89
✓ 352 Hale, NE/4NE/4 sec. 27, T. 31 N., R. 8 W., lease SF-079037	11/18/89
✓ 105 Allison Unit Com, SW/4NE/4 sec. 26, T. 32 N., R. 7 W., lease SF-078483-A	11/20/89

Also returned are your requests for an additional extension that were received after the expiration date. You may resubmit these APDs if you desire to drill at a later date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

Mark Holmes

FOR Ron Fellows
Area Manager

RECEIVED

JAN 10 1990

OIL CON. DIV.
DIST. 3

cc: NMOCN

ABANDONED LOCATION

17201 CHOCUTAS