

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-045-28003
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name:
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		Sly Slav
2. Name of Operator Dugan Production Corp.		8. Well No. #3
3. Address of Operator P.O. Box 420 Farmington, NM 87499		9. Pool name or Wildcat Basin Fruitland Coal
4. Well Location Unit Letter <u>N</u> : <u>1,250</u> feet from the <u>South</u> line and <u>1,800</u> feet from the <u>West</u> line Section <u>13</u> Township <u>30N</u> Range <u>15W</u> NMPM County <u>San Juan</u>		
10. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>5,315' GL</u>		

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Completion <input checked="" type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Pressure test casing 3,000 psi.
2. Run GR-CCL-CNL.
3. Perforate Fruitland Coal 515'-520' & 642'-653' with 2 shots/ft. (36 shots for 18 ft.)
4. Breakdown with 200 gal. 15% HCl followed by Frac 20,000# 20/40 sand in 18,000 gal. 70 quality foam containing 30# linear gel.
5. Job complete 12/14/2001.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry Kochis TITLE Engineer DATE 12/20/2001

Type or print name Terry Kochis Telephone No. (505) 325-1821

(This space for State use)

APPROVED BY CHARLES T. PERREN TITLE SENIOR OIL & GAS INSPECTOR, DIST. I DATE DEC 24 2001

Conditions of approval, if any: