UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Not	cices and Reports	on Wells	* * *	
I. Type of Wel GAS	1		1727	5. 6.	Lease Number SF-078386 If Indian, All. or Tribe Name
. Name of Ope	rator		AU	2000 P	Unit Agreement Nam San Juan 32-9 Unit
BURLI RESOT	NGTON	& GAS COMPANY	G ALO	EIVED ON. DIV	
	1 V	<u> </u>	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		Well Name & Number
	hone No. of Opera 9, Farmington, NM	i i	26-9700/	62171	San Juan 32-9 U#18 API Well No. 30-045-28942
Location of	Well, Footage, S	Sec., T, R, M		10.	Field and Pool
1615'FSL, 1	780'FWL, Sec.17,	T-31-N, R-9-W, N	MPM	11.	Blanco Mesaverde County and State San Juan Co, NM
X Sub Fin Describe 6-28-00	TIH & freepoint tbg. TIH & ca TIH, tag up @ 55 Flow well & CO t Alternate blow &	_X_ Other - Tooleted Operations ods. ND WH. NU Bo tbg. TOOH. TIH, atch fish. Pull to 640'. Blow well a to 6099'. SDON. a flow well. CO to jts 2 3/8" 4.7#	DP. Attempt chemical creation for PBTD @ 66 J-55 tbg,	to TOOH w/that tbg @ 5976 TOOH w/fish. D @ 6099'. SI D99'. SD for set @ 6049'.	rion Fracturing ff Injection Og. Tbg stuck. SDON 7'. TOOH w/2 3/8" SD for weekend. DON. weekend. ND BOP. NU WH. SDO
7-10-00					sea.
Signed 66	certify that the	Title Re		rect. upervisor_Dat	

SMA