Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form	C-103	
Revise	d 1-1-	8

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 OIL CONSERVATION DIVISION

P.O. Box 2088 Santa Fe, New Mexico 87504-2088 WELL API NO.

30-045-28994

5. Indicate Type of Lease _______ STATE ____ FEE X.

6. State Oil & Gas Lease No.

NA

7. Lease Name or Unit Agreement Name

/ 50 Hot	SUNDRY NOTICE	S AND REPORTS OF	N WEL	LS	7//			
(DO NOT USE TH	IS FORM FOR PROPO	ISALS TO DRILL OR TO D	FEDEN	OP BLUG BACK T	OA 7.	Lease Name or Unit A	greement Name	
L	FORM C-101	IR. USE "APPLICATION F) FOR SUCH PROPOSAL	引唱	MAGE! IN	로ツ			1
I. Type of Well:	7. 0.44.0 10	7 ON SOUN PROPUSAL				Texakoma Fai	rmington	:
OIL	GAS X	OTHER	M	MAR 3 0 199	4 9			!
2. Name of Operator		,,			8.	Well No.	· · · · · · · · · · · · · · · · · · ·	
Texakoma O	il and Gas Co	rporation	0	CONL		1		
3. Address of Oberato	x		-					
Une Lincoln	Centre, 5400	LBJ Freeway, Ste	500	Dallas TV	75240	Racin Frui	tland Coal	
4. Well Location	1065		•				Claud Coal	
Unit Letter _	A 1265	Feet From TheN	~	Line and	800	Feet From The _	E	Line
	30	Township 30N	Ra					County
		10. Elevation (Show)				M San Juan		7777777
//////////////////////////////////////								
11.	Check App	propriate Box to Indi	icate N	Nature of Notice	ce. Repo	rt, or Other Date	a	777777
NO.	TICE OF INTER	ITION TO:			=	QUENT REPO		
				,	OODOL.	QUEITI HE)(() O()	_
PERFORM REMEDIAL	_ WORK	PLUG AND ABANDON		REMEDIAL WOF	RK	ALTE	RING CASING	
TEMPORARILY ABAN	DON	CHANGE PLANS		COMMENCE DR	RILLING OP	NS. PLUC	AND ABANDON	MENT _
PULL OR ALTER CAS	ING		_	CASING TEST A	ND CEMEN			
OTHER:					_	· —	rt	X
				OTHER: DITT	I and C	omplete Repo		<u>_</u>
12. Describe Proposed o	or Completed Operations	(Clearly state all pertinent de	iails, an	d give pertinent date.	s, including e	estimated date of starti	ng any proposed	

Spudded well @ 1:15 p.m., MST, on 1-22-94. Drilled 12-1/4" hole to 180' and ran 8-5/8" 24# J-55 ST&C to 179.48'. Guide shoe @ 178.98', insert float @ 141.83' and 2 centralizers @ 142' and 97'. Cmt'd w/130 sx (154 ft³) stand cmt + 2% CaCl + .25#/sx Flocele. Circ 6 Bbl cmt to surf. Bumped plug @ 5 p.m., MST, 1-22-94. Drilled Baffle and tested OK to 1000 psi. Drilled 7-7/8" to 1810' - TD @ 8:30 p.m., MST, 1-23-94. Ran open hole logs. Ran 5-1/2" 15.5# J-55 LT&C w/guide shoe @ 1808.86', insert float @ 1780.1' and 6 centralizers @ 1781', 1694', 1607', 1518', 1432', and 1342'. Cmt'd prod string w/250 sx (458 ft³) Econolite + 2% CaCl + .25#/sx Flocele followed by 100 sx (118 ft³) stand cmt + .6% HALAD-322. Bumped plug to 1500 psi @ 6:49 a.m., MST, 1-24-94. Circ 11 Bbls to surf. Ran GR and CBL. Perf. Fruitland Coal @ 1666-8' and 1682-1706' (6 SPF) on 3-19-94. Performed foam frac. Ran 2-3/8" tbg to 1740' and installed down hole pump.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE Mary Curliss Patton	mme Drilling Manager	DATE 3/28/94				
TYPE OR PRINT NAME Mary Curliss Patton		TELEPHONE NO214/701-9106				

(Thus space for State Use)

Original Signed by CHARLES GHOLSON

TITLE CEPUTY OR & GAS INSPECTOR, DIST BY DATE MAR 3 0 1994

work) SEE RULE 1103.