orm 3160-5 une 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135

panger pari		
Expires:	March	31, 1993
Decisions		Carial Ma

BUREAU OF I	AND MANAGEMENT	5. Lease Designation and Serial No.
SUNDRY NOTICES	AND REPORTS ON WELCS	NM - 0498
	ill or to deepen or reentry to a different reservoir.	6. If Indian, Allottee or Tribe Name
	R PERMIT—" for such proposals	
	WAY 2001	7. If Unit or CA. Account Designation
SUBMIT	IN TRIPLICATE	7. If Unit or CA, Agreement Designation
. Type of Well		
□ Oil 🖂 Gas □		8. Well Name and No.
Weil Other Name of Operator		Federal 8-#3
Texakoma Oil & Gas (amountion	9. API Well No.
3. Address and Telephone No.	· · · · · · · · · · · · · · · · · · ·	30-045-30528
Suite 500, 5400 LBJ Fwy. ,]	Dallas, Tx 75240, (972) 701-9106	10. Field and Pool, or Exploratory Area/Gac
Location of Well (Footage, Sec., T., R., M., or Survey De	escription)	Flora Vista-Fruitland Sand
737' FNL & 1686' FW!	-, Lot C, Section 8,	11. County or Parish, State
Township 30 North, R	•	
,ownship SUNOTIL) R	arge 12 west	San Juan, New Mexico
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	Abandonment	Change of Plans
~	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	Other Cementing Operations	Dispose Water
	0 1	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
	l pertinent details, and give pertinent dates, including estimated date of starting all depths for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled,
-the all was drilled	to total depth at 2185' and og	pulple logs run on
This well was armed	10 placespie a and some of	
april 13, 2001. Pro	duction casing (4/2", 10. Ippf, J-5	so, News was ruc
to 2158 and ce	monted w/a 130 SK C-Lite lead	dslumy and toiled in
1.7/20 Sks Cls B"	, 15.6ppg, 1.18 yield. During con	ment displacement circulati
the Contractorial	est after 12Bb/s of the total	34 Bble. This puts the
To the surface was	from surface , estimated. A GR/C	CL/Bond log will be
top of Cement at 500	At the case the hal	and the Ely "cosing
run this fim. 4-16-	of to verify the cement top bet	The Assertion 175'
MI C - COCING LIMICS	providency run and lemented to-	any acc from 1121
I'M ALAN +5 CEMEN	1 00000	
(F) (7)	at the UV " course to swife	ace as planned,
it possible, and ten	nent the 41/2" casing to surt	1
4. I hereby certify that the foregoing is true and correct	TAM SOPIAIVIE	Compared to the second
Signed Om Spundo	Title Drilling Manager	Date 4-16-2004
(This space for Federal or State office use)	·ine willing it is a few	
	Title	MAY U 2 2001
Approved by	Tiuc	The section of the section (

United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington District Office 1235 La Plata Highway Farmington, New Mexico 87401

IN REPLY REFER TO

MAY - 3

NM-0498 3162.3-1(07100)

Texahoma Oil and Gas Company Attn.: Tom Sprinkle Suite 500, 5400 LBJ Fwy., Dallas, Texas 75240

Dear Mr. Sprinkel:

Reference is made to the following well on Federal oil and gas lease NM-0498:

No. 3 Federal 8, located 737' FNL and 1686' FWL, Section 8, T.30N., R.12W., San Juan County, New Mexico.

This well is within one mile of the Farmington City limits and considered a high priority for Inspection and Enforcement purposes. On April 17, 2001, this office received your after the fact notice that the well had been spudded, surface and production casing strings set and cemented, and the bradenhead squeezed. You indicated that cement bond logs were going to be run to evaluate cement integrity and the results filed accordingly.

This office has no record of prior approval, written or verbal, being given to perform the bradenhead cementing operations. In addition, you failed to notify our office **prior** to spudding the well so a BLM Inspector could be present to inspect the drilling and cementing operations. As such, you are in violation of 43 CFR 3162.3-1, and the General Requirements of the Application for permit to Drill under Part I, F and G., which requires prior notice before conducting drilling operations and approval before conducting remedial cementing operations. This violation will serve as notice that if actions of this sort occur in the future on any operations conducted by your company, you will be subject to an assessment. In addition, you are required to run a cement bond log on this well to determine the overall cement integrity of the well bore. Before your Completion Report will be accepted, you are required to file all cement bond logs run on this well. Enclosed you will find your processed Sundry Notice.

Under provisions of 43 CFR 3165.3, you may request an Administrative Review of the assessment described above. Such request, including all supporting documents, must be filed in writing within 20 business days of receipt of this notice and must be filed with the State Director, Bureau of Land Management, P. O. Box 27115, Santa Fe, New Mexico 87502-0115. Such request shall not result in a suspension of the order(s) unless the reviewing official so determines. Procedures governing appeals from instructions, orders or decisions are contained in 43 CFR 3165.4 and 43 CFR 4.400 et seq.

If you have any questions regarding the above, please contact Jim Lovato @ (505) 599-6367.

Sincerely,

/s/ Jim Lovato

Jim Lovato

Team Leader, Petroleum Management Team

Enclosures (Sundry Notices)

bcc:

I&E: Kelly Well File DOMR

07100:JLovato:5/3/01:Texahoma.violation

NO --