February 04, 2002

30-045-30859

New Mexico Oil Conservation Division 1000 Rio Brazos Road Aztec, NM 87410

> Re: Deviation Record Roddy Production Company, Inc. Raymond Simmons No. 2 Section 17, T30N, R11W San Juan, New Mexico

The following is a summary of the deviation tests run on the subject well:

<u>Depth</u>	Deviation
156'	3/ 4 °
318'	1°
819'	1 1/4°
1319'	1°
1818'	1/2°
2348'	1/2°
2844'	3/4°
3342'	1/2°
3839'	1/4°
4331'	3/4°
4700'	3/4°
5188'	1°
5683'	1/2°
6123'	1°
6558'	Missrun
6777'	1 1/4°

R.E. Fielder

Business Manager

Roddy Production Company, Inc.

MH

Raymond Simmons No. 2 Deviation Record Page Two

Acknowledgment

State of New Mexico

County of San Juan

The foregoing instrument was acknowledged before me on this 4th day of February, 2002 by R.E. Fielder.

Notary Public

My Commission Expires: October 29, 2005

OFFICIAL SEAL'
Norma Jean Schlueter
NOTARY PUBLIC - NEW MEXICO
Notary Bond Filed with Secretary of State
My Commission Expires /0/24/05

MH