

NEW MEXICO  
OIL CONSERVATION COMMISSION  
AZTEC, NEW MEXICO

120 East Chaco  
~~XXXXXXXXXXXX~~

October 8, 1956

El Paso Natural Gas Co.  
Box 997  
Farmington, New Mexico

Att: Mr. E. J. Coal

Dear Mr. Coal:

Packer leakage test recently conducted on your #3-A Sellers well in the SW $\frac{1}{4}$  Section 30-30N-10W, which is a Dual Completion between the Pictured Cliffs and Mesaverde formations, has indicated that there is communication between the tubing and casing.

In accordance with our dual completion orders, we are therefore directing that you take immediate action to separate the two producing zones in this well.

I would suggest that you contact this office after completing your remedial work but before the rig has been released so that you may conduct a packer leakage test while the rig is still on the location.

Yours very truly

Emery C. Arnold  
Supervisor, District #3

ECA:ks

cc: Mr. A. L. Porter  
OCC, Santa Fe, N.M.

NEW MEXICO  
OIL CONSERVATION COMMISSION  
NEW MEXICO

120 East Street  
Albuquerque, New Mexico

October 2, 1950

Mr. J. H. Brown  
Box 237  
Farmington, New Mexico

Dear Mr. Brown:

Dear Sir:

Further research was recently conducted on your #3-A Sellaers well in the SW 1/4 Section 30-30N-10W, which is a Dual Completion between the fractured Cliffs and Mesaverte formations, has indicated that there is communication between the tubing and casing.

In accordance with our dual completion orders, we are therefore directing that you take immediate action to separate the two producing zones in this well.

I would suggest that you contact this office after completing your remedial work but before the rig has been released so that you may conduct a packer leakage test while the rig is still on the location.

Yours very truly

Wm. C. Arnold  
Superintendent, District #3

cc: 100

Mr. J. H. Brown  
Box 237, Farmington, New Mexico