NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

		1	
REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON REPAIRING WELL
REPORT ON RESULT OF PLUGGING WELL	x	REPORT ON RECOMPLETION OPERATION	REPORT ON (Other)
		September 9, 19	355 Astec, New Mexico
Following is a report or	the work done	and the results obtained under the headin	g noted above at the
		·	
	npany or Operator)	orporation	(Lease)
y. B. Umbe	Contractor)	, Well No	in the
T SAN R TO W NM		Pool,	San Juan
The Dates of this work were a	s folows:	ptember 6, 1955	/ NLULIVED
Notice of intention to do the	work (was) (was	not) submitted on Form C-102 on	SEP 3 0 1955
and approval of the proposed			OIL CON. COM.
and approvar or the proposed			DIST. 5
	DETAILED A	CCOUNT OF WORK DONE AND RES	SULTS OBTAIN D
ermanently plug	ged and al	candon with a 72 foot p	olug in bettom. using 12 :
of cement, 4 in top, using 5 lean. Placed 4 lean. Placed 4 lean. Placed 4 lean. Phis well is new released.	formation sacks of inch mar the casing	, 8 in pipe, shuting of sement. Leaving pits a ker 4 feet above ground	s hereby made to have bone
of cement, 4 in top, using 5 lean. Placed 4 lean. P	formation sacks of inch mar the casing	, 8 in pipe, shuting of sement. Leaving pits a ker 4 feet above ground	of water. Put a 50 feet and location leveled and level. I hereby made to have bone
of cement, 4 in in top, using 5 lean. Placed 4 lean	formation sacks of inch mar di casing plugged aught	Basin Natural Gas (Company) I hereby certify	If water. Put a 50 foet and location leveled and level. Thereby made to have bond location. Field. Supt. (Title)
of cement, 4 in in top, using 5 lean. Placed 4 lean	formation sacks of inch mar had easing plugged aught (Name)	Basin Natural Gas (Company) I hereby certify	If water. Put a 50 foet and location leveled and level. Thereby made to have bond location. Field. Supt. (Title)
of cement, 4 in in top, using 5 lean. Placed 4 lean	formation sacks of inch mar had easing plugged aught (Name)	Basin Natural Gas (Company) I hereby certify	ind location leveled and level. hereby made to have bone corp. Field. Supt. (Title) that the information given above is true and corpy knowledge.
of cement, 4 in in top, using 5 lean. Placed 4 lean	formation sacks of inch mar inch mar di casin plugged (Name)	Rasin Natural Gas (Company) I hereby certify to the best of m Position	ind location leveled and level. hereby made to have bone corp. Field. Supt. (Title) that the information given above is true and corpy knowledge.

(Date)

Address...... 109 W. Chaso, Astes, M.M.

· · · ·	·	the particular section of the property of the
		OIL CONSERVATION COMMISSION AZTEC DISTRICT OFFICE No. Copies Peceived
		DISTRIBUTION NO. Sperator Santa Fe
•		Proreting Office State Land Office U. S. G. S. Transporter
•	· 	File

And the second of the second