

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator King Oil

% NMDCI

3. Address and Telephone No. 1000 N. 13th St. Rd.

AZCOC, NM

87410

(505) 334-6178

4. Location of Well (Footage, Sec., T., R., M. or Survey Description)

2310/N * 530/E * 5-30N-17W

5. Lease Designation and Serial No.

14-20-603-2021

6. If Indian, Allottee or Tribe Name

Navajo

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Navajo G #3

9. API Well No.

3004560234

10. Field and Pool, or Exploratory Area

Salt Creek Plateau

11. County or Parish, State

San Juan NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

See Attached

14. I hereby certify that the foregoing is true and correct

Signed NMDCI Plugged Well

Title

Date 1/23/97

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

King Oil Company, Nav G #3, H-05-30N-17W, 30-045-60234

- 12-16-96 Cleaned off location, dug pit, set anchors and dug around old csg. Cut off old csg. and welded collar on csg. Rigged up BOP and WIH with 2 3/8, tbg. fill at 890'. Established circ. down the tbg. and to the surface but couldn't get circ. down the csg. and up the tbg. POH with tbg. and PU four drill collars, bit sub a 4 3/4 bit and the power swivel. WIH and tagged up at 570'. Cleaned out fill to 790', circ. for 15 min. and POH up to drill collars then shut down.
- 12-17-96 WIH to 567' and tagged up. Circ. out fine sand while drilling to 1040'. Circ fine sand to pit for 30 min. and rigged up Cementers Inc. to pump cement thru the drag bit and collars due to sand fill when we trip hole. Cementers twisted driveline on bulk truck and had to call for another truck. Rigged up power swivel to keep sand from plugging bit and bit was already plugged. TOH and bit was plugged with fine sand.
- 12-18-96 WIH with 4 3/4 drag bit and 2 3/8 tbg. to 725' and tagged sand. Rigged up power swivel and cleaned out hole to 1040' with water and polymer to circ. sand out better. Doubled cement volumes on plugs due to sand falling in on us (couldn't tag plugs.) Talked to Wayne Townsend and he agreed. Hole standing full, no fluid loss. Spotted 45 sxs. @ 1040', 45 sxs @ 600' and circ. cement from 126' to the surface with 35 sxs. Installed dry hole marker, removed anchors, covered pit and leveled location.