

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

14-20-603-733

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo

7. UNIT AGREEMENT NAME

Horseshoe Gallup Unit

8. FARM OR LEASE NAME

Horseshoe Gallup Unit

9. WELL NO.

126

10. FIELD AND POOL OR WILDCAT

Horseshoe Gallup

11. SEC., T., R., M., OR BLK. AND  
SUBST. OR AREA

Sec. 5 - 30N - 16W

12. COUNTY OR PARISH 13. STATE

San Juan

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Water Injection

2. NAME OF OPERATOR

ARCO Oil and Gas Company

3. ADDRESS OF OPERATOR

P. O. Box 1610, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*

See also space 17 below)

At surface

Unit "D"

660'

610' FNL & 660' FWL, Sec. 5

RECEIVED

NOV 19 1986

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

14. PERMIT NO.

No API No. Assigned

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

5384' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

Request shut-in status

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

This well was shut in during June 1970, because the production supported by this well made it uneconomical to operate.

This well is in a large Unit which is now under waterflood operations. Waterflood and tertiary recovery studies are currently being conducted. These studies may result in a revised waterflood plan or in a tertiary recovery program that may require the use of this well in order to recover the maximum amount of oil from this reservoir.

Therefore we would like to cancel our approved plans for P&A and request extended shut-in status.

NOV 21 1986

OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

*Ken W. Gossnell*

TITLE

915-688-5672

Engr. Tech. Spec.

DATE

11-12-86

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*John D. Kille*

\*See Instructions on Reverse Side

NMOCO