

Form 9-331b  
(April 1952)

(SUBMIT IN TRIPLICATE)


Indian Agency Navajo

1-100-100-763

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_

Lease No. \_\_\_\_\_



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO _____ <input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 6, 1959

Well No. Navajo D 42 is located 640 ft. from N line and 640 ft. from E line of sec. 36

22 1/4 Sec. 36 (1/4 Sec. and Sec. No.)  
22N (Twp.) 17W (Range) 22N 7W (Meridian)  
Undesignated (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5220 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

**Plan to deepen well from present depth of 640' to test Dakota formation at approximately 1230'. Plan to set 4 1/2" casing to total depth if productive.**



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company KING OIL COMPANY

Address 745 Petroleum Club Bldg.,  
Denver, Colorado

By Bernard King  
Title President

