Form 3160-5		FORM APPROVED /
(June 1990)		Budget Bureau No. 1004-0135
		Expires: March 31, 1993
UNITED STATES		5. Lease Designation and Serial No.
DEPARTMENT OF THE INTERIOR		14-20-604-1951
BUREAU OF LAND MANAGEMENT		6. If Indian, Allottee or Tribe Name
SUNDRY NOTICES AND REPORTS ON WELLS		Ute
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir, Use "APPLICATION FOR PERMIT" for such proposals		7. If Unit or CA. Agreement Designation
SUBMIT IN TRIPLICATE		Horseshoe Gallup Unit
Type of Well Oil Well Gas Well X Other		8. Well Name and No. HGU #199
2. Name of Operator		9. API Well No.
Central Resources, Inc. c/o Playa Minerals & Energy, Inc.		30-045-10121
3. Address and Telephone No.		10. Field and Pool, or Exploratory Area
650 N. Sam Houston Pkwy E. Suite 500 Houston, Tx 77060 (281) 931-3800		Horseshoe Gallup Unit
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
1710' FSL, 2310' FEL, Sec. 33, T31N, R16W		San Juan County, NM
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
į	X Abandonment	Change of Plans
X Notice of Intent	Recompletion	New Construction
	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
Final Abandonment Notice	Other	Dispose Water
		Note: Report results cf multiple completion on Well
12 Describe Propagad or Completed Operation		Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*		
Plug and Abandon per the attached procedures.		
I lug and Abandon per the attached procedures.		
	18 19 20 20	
	4510	
	To and	(Z)
	A LER 200ED	
FEB EIVED RECORDS		
		2
	O Carlo	
	16.5.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4.2.3.4	
	\$ 5.3.4 E	*
		· · · · · · · · · · · · · · · · · · ·
14. I hereby certify that the foregoing is true and correct		
		D . 01/22/01
Signed Lack	Title Regulatory Compliance	Date 01/23/01
Ken Jackson		
(This space for Federal or State offi		2 (12 /2)
Approved by	Title	Date $\frac{2/13/01}{}$
Conditions of approval, if any:		
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,		
fictitious or fraudulent statements or representa	tions as to any manner within its jurisdiction.	

*See Instruction on Reverse Side

Plugging and Abandonment Procedure Horseshoe Gallup Unit No. 199 Attachment "A"

Well Data:

Location:

1710' FSL, 2310'FEL, Section 33 T31N, R16W

San Juan County New Mexico

TD:

1350'

PBTD:

1316'

Surface Casing:

8-5/8", 22.7ppf, H-40 set @ 89' with 70 sacks

Production Casing:

5-1/2", 14ppf J-55 set @ 1344' with 80 sacks

Perforations:

1140'-1182' with 4SPF

1266' -1278' with 4SPF

Procedure:

1. Release packer and TOH w/tubing.

- 2. Trip in hole with cement retainer and set at 1000.'
- 3. Mix and pump 33 sacks of cement below retainer. Pull out of retainer and set 15 sack plug on top of retainer. Estimated top of cement to of cement @ 870'.
- 4. TOH and lay down tubing.
- 5. Perforate squeeze holes at 115'.
- 6. Establish circulation down casing, through annulus and out bradenhead.
- 7. Mix and pump 55 sacks of cement down casing through perforations, into annulus and out through bradenhead. Leave casing and annulus full of cement.
- 8. Cut off casing and install regulation dry hole marker.
- 9. Reclaim location as per BLM regulations.