| Form 9-331 (Maj: 1063) | UNITED STATE | | Form approved. Budget Bureau No. 42-R1424. |
|---|---|--|---|
| | DEPARTMENT OF THE | = ' " | 5. LEASE DESIGNATION AND SERIAL NO. |
| | GEOLOGICAL SURVEY | | 14-08-0001-8200 |
| (Po not use | SUNDRY NOTICES AND REP this form for proposals to drill or to deepe Use "APPLICATION FOR PERMIT—" | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo-Ute Mountain | |
| 1. CAS GAS GAS | | | 7. UNIT AGREEMENT NAME |
| THE L WELL OTHER | | | Horseshoe Gallup Unit |
| 2. NAME OF OPERATOR | | | 8. FARM OR LEASE NAME |
| Atlantic Richfield Company | | | Horseshoe Gallup |
| 3. ADDRESS OF OPERATOR | | | 9. WELL NO. |
| 1860 Lincoln Street, Suite 501, Denver, Colorado 80203 | | | 28 |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit J, 1949' FSL and 1980' FEL, Sec. 31 | | | 10. FIELD AND POOL, OR WILDCAT |
| | | | Horseshoe Gallup 11. sec., T., R., M., OR BLK. AND |
| | | | SURVEY OR AREA |
| | | | Sec. 31-31N-16W |
| 14. PERMIT NO. | 15. ELEVATIONS (Show | whether DF, RT, GR, etc.) | 12. COUNTY OR PARISH 13. STATE |
| | | 5462' GR | San Juan New Mexico |
| | | | shar Data |
| 16. | Check Appropriate Box To Ir | idicate Nature of Notice, Report, or O | iner Daid |
| 16. | Check Appropriate Box To In NOTICE OF INTENTION TO: | | ENT REPORT OF: |
| 16. | NOTICE OF INTENTION TO: | | ENT REPORT OF: |
| | NOTICE OF INTENTION TO: HUT-OFF PULL OB ALTER CASING | SUBSEQU | |
| TEST WATER S | NOTICE OF INTENTION TO: HUT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE | SUBSEQUI WATER SHUT-OFF | ENT REPORT OF: |
| TEST WATER S | NOTICE OF INTENTION TO: HUT-OFF PULL OR ALTER CASING MULTIPLE COMPLETE | WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Shut In E | REPAIRING WELL ALTERING CASING ABANDONMENT* |
| TEST WATER SEFRACTURE TREASHOOT OR ACID REPAIR WELL + Other) | NOTICE OF INTENTION TO: HUT-OFF PULL OB ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS | WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Shut In E | REPAIRING WELL ALTERING CASING ABANDONMENT* Xtension Request of multiple completion on Well tion Report and Log form |

This well was shut in during July 1972 because the production was 100% water.

This well is in a large Unit which is now under waterflood operations. Future plans are to conduct waterflood and tertiary recovery studies. These studies may result in a revised waterflood plan or in a tertiary recovery program that may require the use of this well in order to recover the maximum amount of oil from this reservoir.

TEMPORARY ABANDONMENT EXPIRES JUN 1 197>

Two copies sent to New Mexico Oil Conservation Commission

JUN 1 4 1976
OIL CON. COM.
DIST 3

DATE 6/4/76