

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL OTHER-	7. Unit Agreement Name
2. Name of Operator Union Texas Petroleum	8. Farm or Lease Name Rawson
3. Address of Operator P.O. Box 1290, Farmington, New Mexico 87499	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>810</u> FEET FROM THE <u>North</u> LINE AND <u>1070</u> FEET FROM THE <u>East</u> LINE, SECTION <u>35</u> TOWNSHIP <u>31N</u> RANGE <u>12W</u> N.M.P.M.	10. Field and Pool, or Wildcat Basin Dakota
15. Elevation (Show whether DF, RT, GR, etc.) 5889' GL	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>		COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <u>Redrill</u> <input checked="" type="checkbox"/>		OTHER _____ <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The existing ground bed on this location has failed. To mitigate corrosion to the casing, we intend to redrill the ground bed, next to the existing ground bed, as follows:

1. Drill 6-3/4" hole w/air to \pm 300' or until moisture encountered.
2. Log the well with an anode and place 10 anodes across conductive formations.
3. Run 1" poly vent pipe with holes in anode zone to surface.
4. Backfill with coke breeze slurry.

No new ground will be disturbed.
The estimated date of starting this work will be in April 1985.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED P.A. Morris TITLE DRILLING FOREMAN DATE 4/23/85

APPROVED Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT #3 DATE APR 25 1985

CONDITIONS OF APPROVAL, IF ANY: