



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor

Betty Rivera

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

September 3, 2002

Dolores Silseth
Burlington Res O&G Co
PO Box 4289
Farmington NM 87499

Re: Pierce SRC 2, K-30-31N-10W API 30-045-10271

Dear Dolores:

The Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before November 1, 2002.

Reference RBDMS CTP0224630862 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

A handwritten signature in cursive script that reads "Charlie T. Perrin".

Charlie T. Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mpk

CC: CTP
Well File