



STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE

BRUCE KING  
GOVERNOR  
LARRY KEHOE  
SECRETARY

1000 RIO BRAZOS ROAD  
AZTEC, NEW MEXICO 87410  
(505) 334-6178

November 12, 1981

B. O. A. Oil & Gas Co.  
3539 East 30th Street  
Farmington, NM 87401

Re: Ute Mtn. B #2 F-29-31N-15W

Gentlemen:

Enclosed are copies of Inspection Ticket forms which report conditions found recently by Division personnel at installations operated by your company.

You are requested to take corrective action as indicated by the information on the form. Conditions which are specific violations of the Oil Conservation Division Rules and Regulations are circled on the form and should be corrected immediately. Follow-up inspections will be made in the near future.

You are requested to notify this office by mail when the corrective actions have been completed.

If you have questions concerning any specific item on the form, please contact us.

Yours truly,

Jeff A. Edmister  
Deputy Inspector

JAE:gc

Enc.

cc: / Well file  
Operator file

## INSPECTION TICKET

DATE 1-10-81INSTALLATION Ute Mt. R #2LOCATION F-29-317-19WOPERATOR BCA Oil & Gas Inc.NEEDS SIGN OKPOOL VerdeFORMATION GallupLOCATION:CLEAN        JUNKY        WEEDS       OIL & WATER SPILL ✓EDGES       GENERAL APPEARANCE       PITS: NADIKE GOOD        NEEDS WORK       FENCE GOOD        NEEDS WORK       CONTAINS OIL        AMOUNT       CONTAINS WATER        AMOUNT       PRODUCTION EQUIPMENT:PUMP        BELT GUARD        FENCE       SEPARATOR        DEHY        COMP       CLEAN        DIRTY        WEEDS       SAFE        FIRE HAZARD       PIPED TO PIT        TANK       LEAKS ✓FLOWS TO PIT        GROUND       CATHODIC PROTECTION UNIT       TANKS: NANUMBER        SIZES       CLEAN        DIRTY       OVERFLOW TO PIT       LOAD LINE OK        PUDDLES OF OIL       LEAKS        FIRE HAZARD       FIRE WALLS        GOOD        NEED WORK       FIRE WALL REQUIRED        RECOMMENDED       INSPECTED BY Jeff A. EdmisterOWNER NOTIFIED BY MAIL, PHONE, DATE 11-10-81 OFFICE AztecOTHER REMARKS:

The packing box is leaking. There is two small dikes made with a shovel to contain the oil, but it has went over both. It is now going towards the array.