Form 3160-5 FORM APPROVED (June 1990) Budget Bureau No. 1004-0135 Expires: March 31, 1993 **UNITED STATES** 5. Lease Designation and Serial No. DEPARTMENT OF THE INTERIOR 14-20-603-734 **BUREAU OF LAND MANAGEMENT** 6. If Indian, Allottee or Tribe Name SUNDRY NOTICES AND REPORTS ON WELLS Navajo Do not use this form for proposals to drill or to deepen or reentry to a different reservoir, 7. If Unit or CA. Agreement Designation Use "APPLICATION FOR PERMIT--" for such proposals SUBMIT IN TRIPLICATE Horseshoe Gallup Unit 1. Type of Well 8. Well Name and No. WIW Oil Well Gas Well X Other **HGU #7** 2. Name of Operator 9. API Well No. Vulcan Minerals & Energy, Inc. 30-045-10383 3. Address and Telephone No. 10. Field and Pool, or Exploratory Area 650 N. Sam Houston Pkwy E. Suite 500 Houston, Tx. 77060 (281) 931-3800 Horseshoe Gallup Unit 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 1980' FNL, 2067' FWL, Sec. 30, T31N, R16W San Juan County, NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Abandonment Change of Plans X Notice of Intent Recompletion New Construction Plugging Back Non-Routine Fracturing Subsequent Report Casing Repair Water Shut-Off Altering Casing Conversion to Injection Final Abandonment Notice Other Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* Vulcan plans to plug and abandon this well per the attached procedures. 14. I hereby certify that the foregoing is true and correct Title Regulatory Compliance Signed X Date 08/14/01

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any manner within its jurisdiction.

Title

(This space for Federal or State office use)

Conditions of approval, if any:

Approved by

\*See Instruction on Reverse Side

Date

## Plugging and Abandonment Procedure Horseshoe Gallup Unit No. 7 Attachment "A"

## Well Data:

Location: 1980' FNL, 2067' FWL, Section 30 T31N, R16W

San Juan County New Mexico

TD: 1605' PBTD: 1560' CmtRet: 1473'

Surface Casing: 8-5/8", 24 #/ft, J-55 set @ 131' with 125 sacks

Production Casing: 5-1/2", 14 #/ft, J-55 set @ 1598' with 135 sacks

Perforations: 1518' – 1545' with 2SPF Closed by CmtRet 12/27/93

1398' - 1430' with 2SPF

## Procedure:

Release packer and TOH w/tubing.

Trip in hole with cement retainer and set at 1350'. Circulate hole and pressure test casing.

Mix and pump 33 sacks of cement below retainer. Pull out of retainer and set 25 sack plug on top of retainer. Estimated top of cement @ 1225'.

Trip out of hole and lay down tubing.

Perforate squeeze holes 180'

Establish circulation down casing, through annulus and out bradenhead.

Mix and pump 50 sacks of cement down casing through perforations, into annulus and out through bradenhead. Leave casing and annulus full of cement.

Cut off casing wellhead and install regulation dry hole marker.

Reclaim location as per BLM regulations.