Form 9-331 (May 1963)

UNITED STATES DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

14-08-0001-8200

14-08-0001-8200						
6.	IF	INDIAN,	ALLOTTEE	OR	TRIBE	NAME

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
not nea this form fo					

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

_	use APPLICATION FOR PERMIT—" for such proposals.)	Navajo-Ute Mountain	
1.	WELL GAS OTHER Injection	7. UNIT AGREEMENT NAME	
2.	Atlantic Richfield Company	Horseshoe Gallup Unit 8. FARM OR LEASE NAME	
3.	ADDRESS OF OPERATOR	Horseshoe Gallup 9. WELL NO.	
4.	1860 Lincoln Street, Suite 501, Denver, Colorado 80203 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface	152 10. FIELD AND POOL, OR WILDCAT	
	Unit F, 1980' f/North & 3300' f/East lines Section 28	Horseshoe Gallup 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA	

Sec 28-31N-16W

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH | 13. STATE 57561 <u>San Juan</u> <u>New Mexico</u>

16.

14. PERMIT NO.

2.

3.

4

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF	55 51.55.00	
FRACTURE TREAT	MULTIPLE COMPLETE		FRACTURE TREATMENT	REPAIRING WELL ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING	ABANDONMENT*	-
REPAIR WELL	CHANGE PLANS		(Other) Shut In. ext	ension request	
(Other)		نيا	(Note: Report results of r Completion or Recompletion	multiple completion TIT-II	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.).

Production supported by this well makes it uneconomical to operate. The well was shut in 6-12-70. U.S.G.S. approval dated 6-25-70.

This well is in a large Unit which is now under waterflood operations. Future plans are to conduct waterflood and tertiary recovery studies. These studies may result in a revised waterflood plan or in a tertiary recovery program that may require the use of this well in order to recover the maximum amount of oil from this reservoir.

TEMPORARY ADAMS AND ADMENT **EXPIRES**

Two copies sent to New Mexico Oil Conservation Commission

18. I hereby certify that the foregoing is true and correct SIGNED ___ TITLE Operations Manager W. A. Walther, Jr. This space for Federal or State office use) APPROVED BY _ DATE _ CONDITIONS OF APPROVAL, IF ANY: