#### (SUBMIT IN TRIPLICATE)

# 30

# UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Indian Agency
Ute Mountain Tribal
Allottee
Lease No. 14-20-601-84

# SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	()
1	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO COMMUC FLANG	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLINE OF REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY.
NOTICE OF INTENTION TO ABANDON WELL	10 v 2 5 1952
iona of management	
(INDICATE ABOVE BY CHECK MARK	NATURE OF REPORT, NOTICE, OR OTHER DATA) NEW MEXICO
	November 2h 19_58
	NOVERDER 211
/ell No is located 660 ft. from	om N line and 1980 ft. from W line of sec30 (Meridian)
(72 Bec, and Box 110.)	San Juan New Next co
Yerds-Gallup (County	or Subdivision) (State or Territory)
e Gallup formation in open hole.	to estimated depth of 3800'. Sand oil frac
3-3/8" O.D. at 100' w/125 ax. regula	ar cement, circulated to surface.
1.3/1,4 0.D. at 1100'. no cement. W	ill pull when complete.
)-3/4" O.D. at 1100', no cement. W	ill pull when complete.
0.3/4 0.D. at 1100', no cement. W 0.5/8 0.D. at 2600', no cement. W 0.5/2 0.D. at 3650', set D.V. tool	ill pull when complete.
0-3/4" 0.D. at 1100', no cement. W	ill pull when complete.
0-3/h* 0.D. at 1100', no cement. W 3-5/8" 0.D. at 2600', no cement. W 5-1/2" 0.D. at 3650', set D.V. tool and 100 sx. above tool.	ill pull when complete. ill pull when complete. at 25%), and two stage cement s/50 sx. bel
=3/li 0.D. at 1100', no cement. W =5/8" 0.D. at 2600', no cement. W =1/2" 0.D. at 3650', set D.V. tool and 100 sx. above tool.	ill pull when complete. ill pull when complete. at 25%), and two stage cement s/50 sx. bel
-3/h 0.D. at 1100', no cement. W -5/8" 0.D. at 2600', no cement. W -1/2" 0.D. at 3650', set B.V. tool and 100 sx. above tool.	ill pull when complete. ill pull when complete. at 25%), and two stage cement s/50 sx. bel to this well.
-3/4" O.D. at 1100', no cement. W -5/8" O.D. at 2600', no cement. W -1/2" O.D. at 3650', set B.V. tool and 100 sx. above tool.	ill pull when complete. ill pull when complete. at 25%), and two stage cement s/50 sx. bel to this well.
-3/4" O.D. at 1100', no cement. W -5/8" O.D. at 2600', no cement. W -1/2" O.D. at 3650', set B.V. tool and 100 sx. above tool.	ill pull when complete. ill pull when complete. at 25%), and two stage cement s/50 sx. bel to this well.
-3/h 0.D. at 1100', no cement. W -5/8" 0.D. at 2600', no cement. W -1/2" 0.D. at 3650', set B.V. tool and 100 sx. above tool.	ill pull when complete. ill pull when complete. at 25%), and two stage cement s/50 sx. bel
1 understand that this plan of work must receive approval	ill pull when complete.  at 25%), and two stage cement s/50 sx. bel  to this well.  In writing by the Geological Survey before sperations May Begomminged
3-3/1* 0.D. at 1100', no cement. W. 3-5/8* 0.D. at 2600', no cement. W. 5-1/2* 0.D. at 3650', set B.V. tool and 100 sx. above tool.  The NE NW of Section 30 is dedicated.  I understand that this plan of work must receive approval in the company	ill pull when complete.  at 25%), and two stage cement s/50 sx. bel  to this well.  In writing by the Geological Survey before operations stay be somminged.  Gas Company
3-3/h 0.D. at 1100', no cement. W 3-5/8" 0.D. at 2600', no cement. W 5-1/2" 0.D. at 3650', set B.V. tool and 100 sx. above tool. he RE NW of Section 30 is dedicated	ill pull when complete.  at 25%), and two stage cement s/50 sx. bel  to this well.  In writing by the Geological Survey before operations stay be somminged.  Gas Company
1 understand that this plan of work must receive approval is company  Three States Natural Address  P. O. Box 67	ill pull when complete.  at 25%), and two stage cement s/50 sx. bel  to this well.  In writing by the Geological Survey before aperations way begomment of the company  Original signed by W. D. Bellmon
i understand that this plan of work must receive approval is company	ill pull when complete.  at 25%), and two stage cement s/50 sx. bel  to this well.  In writing by the Geological Survey before perations stay be somminged.  Gas Company  Original signed by W. D. Bellmon
1 understand that this plan of work must receive approval is company  Three States Natural Address  P. O. Box 67	ill pull when complete.  at 2550, and two stage cement s/50 sx. bel  to this well.  In writing by the Geological Survey before perations stay be somminged.  Gas Company  Original signed by W. D. Bellmon  By
1 understand that this plan of work must receive approval is company  Three States Natural Address  P. O. Box 67	ill pull when complete.  at 25%), and two stage cement s/50 sx. bel  to this well.  In writing by the Geological Survey before aperations way begomment of the company  Original signed by W. D. Bellmon

U. S. GOVERNMENT PRINTING OFFICE 16-8437b-8

• • •

## NEW MEXICO OIL CONSERVATION COMMISSION

### Well Location and Acreage Dedication Plat

Section A.						Date Nov. 24, 1958					
Operat	tor	Three	States Natural	Gas Com	nanw I	ease	Ute Mounta	ain Tri	bal		
Well N	No.	1.	_ Unit Letter	Sect	ion 30		Township	31	NorthRangel	l. West	NUPM
			Feet From_			200			est.		Line
County	V	Total	G. L. 1	levation	EEE2	De De	dicated Ac				Acres
Name o	f Prod	ucing	Formation Ga	llun	ــــــــــــــــــــــــــــــــــــــ		ol	_		<del></del>	ACLED
1.	Is the	o Oper	ator the only own	ner* in th	e dedicat	ed acrea	ge outlined	d on the	plat below	?	<del></del>
			No						-		
2.	If the	answ	er to question on	e is "no,	have the	interes	ts of all t	he own	ers been con	solidat	ed
	by con	munit	ization agreemen	nt or othe	rwise? Ye	5	No	If ans	wer is "yes,		
			nsolidation								
3.	If the	answ	er to question tw	o is "no,	list all	the owner	ers and the	ir resp	ective inte	rests b	elow:
			Owner		FOT!		Lan	d Desc	ription		
					oti ti	NEV/					
		<del></del>		/	KLUL	A FR	<b></b>		PECE	VED	· .
				- 1			1		To receive the control of the contro	VEL	,
					DEC 1_1	L 1958	<u> </u>				
					OIL CON	LOOM	į		2 5	1958	
				\	<u> </u>	3 -4	;		- ULOGIUM		-
Section	on. B							( m) (	RINGTON NEI	N MEV	ा २०
				er .					(41,)	A MEVIC	JU.
		i	,	<b>N</b>		, {					
ļ		i	660'	ll .		; {	]	This	s is to cert	ify the	it the
j			1	li .		1 4		info	rmation in	Section	1 A
k	/	980'-	<b>-</b>	¥		[	į.	abor	re is true a	nd comp	lete
ľ						1	i		he best of my	_	
		- 1				1			belief.	11.10 # 10	450
		h		1		1		and	perior.		
L				<u> </u>		<u>L</u>		ጥከም	ee States N	nt Ga	c (Co
								1111	(Operat		5 00,
1		i				1.			(Operat	.01)	
		i				i			A. BOOD		
						1		_1			
		į		1		1	1		(Represent	ative)	
1		.				1		D	47 Tr		AF 16
1		1		.1_		1		FOX	67, Farmin		N • 10 •
				0		<u> </u>			Addre	SS	
ŀ		,		1				<b></b>	· · · · · · · · · · · · · · · · · · ·	illia	
I		j				1			is to	hat	t the
1		ļ			-		٠.	well	location		<b>t</b> he
l		ļ		1	A STATE OF THE STA	1 1		plat	in lon		tted
l								fron	field nome	LOT A	<b>6</b> 1
		Ì							eys hade		Edan
		1	1		19/	12	F2 \ \ \ \ \ \				2 4 4 4
				•	1 2	50.			upodasion		the
				+		P12 -49-	· <del>-</del>		is	シンシ	r to
1					1 0	* ~ ~ ~ ~ ~	· /		best		se and
1					<b>\</b> '	100		beli		***************************************	
1		j			\	7	/	Date	Surveyed Fe	b. 6,1	958
1				1:						~ . ~!	A
1			, 			1		On	eil V. Co	ohsh.	wife
1			•			ł	i	Erne	st V. Echoh	awk	
1				1		1			stered Land		vor.
L						L.	لــــــا	0-		, 0	
								Cent	ificate No.	1545	
-				_				061.0	TITCOLD NO.	<u> </u>	