

5 BLM -Durango 1 File  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry Hole		5. LEASE DESIGNATION AND SERIAL NO. 14-20-604-1951
2. NAME OF OPERATOR Dugan Production Corp.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Ute Mtn. Tribe
3. ADDRESS OF OPERATOR P O Box 208, Farmington, NM 87499		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FNL - 990' FEL		8. FARM OR LEASE NAME Horseshoe
14. PERMIT NO.		9. WELL NO. 280
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5530' GL		10. FIELD AND POOL, OR WILDCAT Horseshoe Gallup
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 27, T31N, R16W, NMPM
		12. COUNTY OR PARISH San Juan
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐

REPAIRING WELL

☐  
☐  
☒

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well was plugged and abandoned as follows:

- 1.) Spotted 25 sacks cement plug (30 cf) 1656 to 1333'.
- 2.) Spotted 100' cement plug with 10 cf from 100' to surface.
- 3.) Installed dry hole marker.
- 4.) Cleaned location of trash. Will notify T.E. Taylor with BIA before restoring location.

Note: Left 9.2#<sup>+</sup> mud between plugs.

APPROVED TO THE PLUGGING OF THE  
WELL BORE ONLY. LIABILITY UNDER  
THE BOND RETAINED UNTIL SURFACE  
RESTORATION IS COMPLETED AND  
APPROVED.

RECEIVED  
Bureau of Land Management

JUN 05 1985

18. I hereby certify that the foregoing is true and correct

SIGNED

*Jim L. Jacobs*  
Jim L. Jacobs

TITLE Geologist

DATE 6-4-85

(This space for Federal or State office use)

APPROVED BY L. Mark Hollis  
CONDITIONS OF APPROVAL, IF ANY:

TITLE ACTING AREA MANAGER

DATE NOV 02 1987

APPROVED  
AS AMENDED

\*See Instructions on Reverse Side

N.M.C.D.

## CONDITIONS OF APPROVAL AND ADDITIONAL REQUIREMENTS

1. This Subsequent Report of Abandonment (SRA) is approved to the plugging of the well bore only. Liability under the bond is retained until surface restoration is completed and approved.
2. Once the dirt work has been completed, the operator will submit Form 3160-5, Sundry Notice, informing the Bureau of Land Management (BLM) of this operation. This Sundry Notice, or Second Subsequent Report of Abandonment (SSRA) will be an acceptance rather than an approval action. (Instruction Memorandum No. CO-87-417).
3. Form 3160-5, Sundry Notice, will be submitted when all restoration is completed. This Sundry Notice, or Final Abandonment Notice (FAN), will be submitted only when the site is ready for inspection by an official of the BLM.
4. PHASED RELEASE OF BOND LIABILITY - After proper plugging of the leasehold's well(s), and after the site has been stabilized and seeded, a percentage of the bond liability can be released. Operators who wish to request partial liability release of a single lease bond may delay filing Form 3160-5, Second Subsequent Report of Abandonment (SSRA) until after the site has been reseeded. In this case, the Sundry Notice should not only detail work that was done but also request partial bond liability release. (Instruction Memorandum No. CO-87-307).