

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San Joaquin Co.

Lease No. 27 878404

Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 3, 19 57

Well No. 1-24 is located 790 ft. from N line and 1490 ft. from E line of sec. 24


21-24 (1/4 Sec. and Sec. No.) 314 (Twp.) 1 (Range) 24N (Meridian)  
Blanco Mesa Park (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 3817 ft. 23

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After running final logs at ID of 6775, the open hole section below 7" casing at 4954' was plugged by placing a 45 sack cement plug over the top of sands at 6420' and a cast iron bridge plug was set in the 7" casing at 4950'. Two sacks of cement were placed on the plug with a dump bucket. This operation followed conversation between Mr. P. J. McKeith and C. E. Carrington.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company COLORADO WESTERN EXPLORATION, INC.

Address 312 U. S. National Bank Bldg.

Denver 2, Colorado

By E.A. Truchess, Jr.

Title President