NO. OF COPIES RECEIVED	3		Form C-103 Supersedes Old
DISTRIBUTION			C-102 and C-103
SANTA FE		NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	1		The state of the s
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE		•	State   Seucral Fee
OPERATOR			5. State Oil & Gas Lease No.
			······································
	SUNDRY NO	OTICES AND REPORTS ON WELLS  .s to drill or to deepen on Plug BACK to a different reservoir.  .s permit -" (Form C-101) for Such PROPOSALS.)	
1.			7. Unit Agreement Name
OIL GAS WELL WELL		THER-	
2. Name of Operator		,	8. Farm or Lease Name
0.00	orad ja	37 <b>05</b> A	v. 1s
3. Address of Operator	9. Well No.		
. 7x 000, sassing bod, ew exter			
4. Location of Well	51,	CW CAIGO	10. Field and Pool, or Wildcat
		and the second s	To me tame and
UNIT LETTER		FEET FROM THE FEET F	THE THE THE MOST
70 77			
THE 1030 LI	NE, SECTION	TOWNSHIP RANGE	1PM. (
minimum.	mm	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	71.11111		
•		opriate Box To Indicate Nature of Notice, Report or	·
NOTIC	E OF INTER	NTION TO: SUBSEQUE	ENT REPORT OF:
_	_		_
PERFORM REMEDIAL WORK	]	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	]	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	]	CHANGE PLANS CASING TEST AND CEMENT JOB	
		OTHER	[
OTHER			
		ons (Clearly state all pertinent details, and give pertinent dates, inclu	ding estimated date of starting any propos
work) SEE RULE 103.	npleted Operation	ons (Clearly state all pertinent details, and give pertinent dates, inclu	ating estimated date of starting any propos
	•	Company of the Compan	
This notice	supercede	s the notice of plug and abandonment subm	itted for this well on
Fabracy 10	1967. T	nformation, not available at that time tu	e to a loss of the con-
cours operat	ions in a	ddition to those of the previous submitte	
PHOMP OF CITTO	10.15 111 4		KITATO /
mida wall ba	a boon ni	ugged and abandoned in the following mann	er:
This well ha	s reen br	agget and abandonous In one I amend	9 3 0 € 196 <b>7</b>
	t	3 blowout preventer	OH 004
Killed well, installed blowout preventer.			OIL CON COM
Spotted 50 s	ack plug	on bottom down tubing.	DIST. 8
Cut tubing a	+ 14531	mixed 100 sacks cement and displaced down	tubing to 1576', 60
Cut tubing a	incian tu	bing, 40 sacks across 5" liner shoe. Rig	caught fire while
sacks left	Instac ou	down tubing	
spotting ce	ment prug	down tubing.	11201
Cut tubing a	it 1576'.	Perf. 7" casing at 1220', set cement ret	ainer at 1139, pumped
150 angles o	omant in	holes at 1200'. Bridge broke loose betwe	en 7 and 9 3/6, annulus
pumped into	7" casin	ng above retainer, circulated out bradenhe	ad. Cemented annulus
w/375 sacks	cement.	Cement circulated.	· 일도성화면 회원 수있절일
"/J!/ Dasa	hood	otted 10 sack surface plug w/4" x 4' P & A	marker.
Cut off well	nead, spo	Joven to Back Battace brue "/ 1 1 a .	
18. I hereby certify that the i	nformation abov	ve is true and complete to the best of my knowledge and belief.	· ·
,		· · · · · · · · · · · · · · · · · · ·	
SIGNED		TITLE STROLEUM SUITGES	DATE
		1 /	. •
(n)	01	1. 1. D'+ TI	
APPROVED BY	11/1/1	Under TITLE Stip Vis 1 !!	DATE
CONDITIONS OF APPROVA	I IE ANY		
CONDITIONS OF APPROVA	T. IF ANT	•	
. /			