

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
Southland Royalty

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
1520'FNL, 1570'FWL Sec.24, T-31-N, R-12-W, NMPM

5. Lease Number
SF-077652
6. If Indian, All. or
Tribe Name
7. Unit Agreement Name
8. Well Name & Number
East #19
9. API Well No.
30-045-20535
10. Field and Pool
Aztec Pic.Cliffs
11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent

☒ Abandonment

☐ Change of Plans

☒ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging Back

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

☐ Other -

13. Describe Proposed or Completed Operations

09-23-92 MOL&RU. Blow down. Kill w/22 BW. ND WH. NU BOP. TOOH w/1" tbq.
09-24-92 Set cmt ret @ 2195'. Test tbq, ok. Est rate into formation. Cmt
plug #1 w/71 sx, 66 sx below ret, 5 sx on top of ret. PU to
2101'. Spot 21 bbl. 9# 50 vis mud 2101-1048'. Perf 2 holes @
1048'. Set cmt ret @ 988'. Est circ out perf & bradenhead. Cmt
plug #2 w/166 sx, 144 sx under ret until approx 1 bbl cmt
returned out bradenhead, spot 22 sx on top of ret. TOOH to 712'.
Circ hole w/9# 50 vis mud. TOOH to 168'. Cmt plug #3 w/13 sx cmt
168'-surface. Cut off WH. Install dry hole marker. Released rig.
Well plugged & abandoned.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Affairs Date 9/25/92

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

CONDITION OF APPROVAL, if any:

APPROVED

SEP 28 1992

AREA MANAGER

