

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIG BRAZOS ROAD AZTEC NEW MEXICO 87410 (505) 334-6178

May 8, 1985

Ms. Barbara Norman Union Texas Petroleum Corp. P.O. Box 1290 Farmington, NM 87499

Re: Taliferro #5M I-30-31N-12W

Dear Barbara:

The 1985 packer leakage test on the referenced well indicates communications between the producible zones. In order to comply with Rule 112-A and the order authorizing the multiple completion, you are hereby directed to initiate remedial activity as soon as possible.

Yours truly,

Charles Gholson

Oil & Gas Inspector

CG/dj

xc: Well File