



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**GARY E. JOHNSON**  
Governor  
**Jennifer A. Salisbury**  
Cabinet Secretary

**Lori Wrotenbery**  
Director  
**Oil Conservation Division**

September 20, 2000

Patsy Clugston  
Phillips Petroleum Company  
5525 HWY 64 NBU 3004  
Farmington NM 87401

Re: San Juan 32-7 #69, B 35-32N-07W API 30-045-24777

Dear Ms. Clugston:

The Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before November 15,

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely,

A handwritten signature in cursive script that reads "Charlie T. Perrin".

Charlie T Perrin  
Deputy Oil & Gas Inspector  
cperrin@state.nm.us

CTP/mk

CC: CTP  
Well File