Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I	OIL CONSERVA	TION DIVISION			
P.O. Box 1980, Hobbs NM 88241-1980	1980, Hobbs NM 88241-1980 2040 Pacheco St.		WELL API NO.	045 05400	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe,	NM 87505		-045-25108	
•			5. Indicate Type	STATE	FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	e •		6. State Oil & Ga	· · · · · · · · · · · · · · · · · · ·	TLL
SUNDRY NOTION (DO NOT USE THIS FORM FOR PRODIFFERENT RESER (FORM C-	CES AND REPORTS ON	WELLS			
(DO NOT USE THIS FORM FOR PRO	POSALS TO DRILL OR TO DEE	PEN OR PLUG BACK TO A	V Lease Name o	or Unit Agreement Nam	<i></i>
(FORM C-	101) FOR SUCH PROPOSALS.		Qulpepper Ma	-	
1. Type of Well:			Man pepper 11	31 C 111	
WELL WELL X	OTHER	JUN 2 8 1999	x 41		
2. Name of Operator ENERGEN RESOURCES CORPORATION	<u> </u>	on con br	8. Well No.		
3. Address of Operator 2198 Bloomfield Highway, Farr	nington, NM 87401	DEG. 3	9. Pool name or Blanco MV/Ba		
4. Well Location Unit Letter F . 1800	Non	th			~
Unit Letter F : 1800	Feet From TheNOT	th Line and 17	Feet From	m The West	Line
Section 7	Township 31N	Range 12W	NMPM	San Juan	County
	10. Elevation (Show v	whether DF, RKB, RT, GR, etc 5834 GL	c.)		
11. Check Apr	propriate Box to Indic		Report or (
NOTICE OF IN		SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	DI LIC AND ADANDON	7			
	PLUG AND ABANDON L	REMEDIAL WORK	<u>ا</u> ۔۔ا	ALTERING CASING	
TEMPORARILY ABANDON L.	CHANGE PLANS L	COMMENCE DRILLING	OPNS.	PLUG AND ABANDO	NMENT
PULL OR ALTER CASING L		CASING TEST AND CE	MENT JOB		
OTHER:		OTHER: Downhole	Commingle		X
12. Describe Proposed or Completed Opera work) SEE RULE 1103.	ations (Clearly state all pertiner	t details, and give pertinent da	tes, including estim	ated date of starting a	ny proposed
In accordance to DHC-2139	this wall was downho	le commingled as foll	0140		
in deed dance to bhe 2133	, this well was downho	re commingred as roll	DWS:		
6/17/99 MIRU. TOH and lay	down MV tubing string.	Pickup long string -	stuck R.U. F	reepoint truck.	Stuck at
44/0'. Perf. 2 holes at 4	680'. Circ. hole with	air. Cut off tubing a	t 4792'. Work	pipe free.	
6/18/99 TOH. TIH with ove	rshot. Catch fish. Jar	loose. TOH. Pick up	packer milling	g assembly.	
6/19/99 TIH. Engage packe out to 6950' with air mis	r and mill out model "	r packer at 4815'. To	JH. TIH and ta	ag fill at 6895	'. Clean
6/21/99 Ran 221 jts., 2 3		set at 6872' Install	single wellh	hea	
	, - ,,	000 ut 00/2 . 1/13tu//	Single wellik	eau.	
I hereby certify that the information above is true	e and complete to the best of my know	vledge and belief.			
SIGNATURE MONICE Ja	rylo	TΠLE Production Assi	<u>stant</u>	DATE6/2	4/99
TYPE OR PRINT NAME Monica Taylor	·			TELEPHONE NO. 505-	325-6800
(This space for State Use)					
ORIGINAL SIGNED BY E	RNIE BUSDH	DEPUTY OIL & GAS IN	SPECTOR, DIST. 1	43 .1111	() 43 = -
APPROVED BY		TITLE		DATE	8 1999