

F

30-045-27000

8-1-88

F. Loc. 1180/S; 970/W Elev. 6377 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. Cu. ft. Cu. ft.
 Casing S. @ _____ W _____ Sx. Int. @ _____ W _____ Sx. Pr. @ _____ W _____ Sx. T. @ _____
 Csg. Perf. Prod. Stim.

Grav. _____ 1st Del. Gas _____
 I.P. _____ BO/D _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS	NITD X	Well Log	TEST DATA							Ref.No.
Ojo Alamo	C-103 ✓	Plat X ✓	Schd.	PC	Q	PW	PD	D		
Kirtland	C-104	Electric Log								
Fruitland		C-122								
P.ured Cliffs	Ditr	Dfa								
Chacra	Datr	Doc								
Cliff House	<div style="text-align: center;"> <p>7-31-90</p> <p>6/3/5.75</p> <p>Acres 156.57</p> </div>									
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										

R-8768

Basin Fr. Coal Co. SJ S 23 T 31N R 10W U M Oper. Meridian Oil Inc. Lse. Atlantic B Com No. 205

Atlantic B Com #205

M-23-31N-10W

MERIDIAN OIL INC.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA
1235 LAPLATA HIGHWAY
FARMINGTON, NEW MEXICO 87401



IN REPLY REFER TO:

NM-013688 (WC)
3162.3-1.0 (019)

CERTIFIED - RETURN RECEIPT REQUESTED
P 565 332 744

AUG. 21 1990

Meridian Oil Incorporated
P. O. Box 4289
Farmington, NM 87499

Gentlemen:

Enclosed is your Application for Permit to Drill (APD) well No. 205 Atlantic "B" Com, SW/4SW/4 section 23, T. 31 N., R. 10 W., San Juan County, New Mexico, lease NM-013688. As discussed with Peggy Bradfield of your company on August 1, 1990, the subject APD is rescinded and returned due to drilling not being commenced within the second extension of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,

John L. Keller, Chief
Branch of Mineral Resources

Enclosure

cc: New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM
87410

ABANDONED LOCATION

RECEIVED
AUG 22 1990
OIL CON. DIV.
VOLUME 3