UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	ces and Reports on	wells	
		5.	Lease Number SF-078651
Type of Well GAS		6.	If Indian, All. or Tribe Name
		7.	Unit Agreement Name
2. Name of Operator			
RESOURCES OIL &	GAS COMPANY	۰	Well Name & Number
3. Address & Phone No. of Operato	or		Richardson #100
FO Box 4289, Farmington, NM 87499 (505) 326-9700 4. Location of Well, Footage, Sec., T, R, M 1070'FNL, 1355'FEL, Sec.15, T-31-N, R-12-W, NMPM		00 9.	API Well No. 30-045-27387
			. Field and Pool
		1:	Basin Fruitland Coa . County and State San Juan Co, NM
12. CHECK APPROPRIATE BOX TO IND	ICATE NATURE OF NOT	ICE, REPORT, OTH	ER DATA
Type of Submission	Type of	Action	
X Notice of Intent	_X_ Abandonment Recompletion	Change of New Constru	
Subsequent Report	Plugging Back	Non-Routine	e Fracturing
	Casing Repair		
Final Abandonment	Altering Casin	g Conversion	to injection
	Other -		
13. Describe Proposed or Compl			
13. Describe Proposed or Compl It is intended to plug and wellbore diagram wi	eted Operations abandon the subject		ed procedure and
It is intended to plug and	eted Operations abandon the subject		ed procedure and
It is intended to plug and	eted Operations abandon the subject		√ ⊃
It is intended to plug and	eted Operations abandon the subject		97 117
It is intended to plug and	eted Operations abandon the subject		√ ⊃
It is intended to plug and	eted Operations abandon the subject		97 117
It is intended to plug and	eted Operations abandon the subjection of the subjection of the submitted by	7-15-97. CON. DIV.	97 117
It is intended to plug and	eted Operations abandon the subjection of the subjection of the submitted by	7-15-97. CENVED AY 3 0 1997	97 117
It is intended to plug and wellbore diagram wi	abandon the subjectiful be submitted by	7-15-97. CENVER AY 3 0 1957 CON. DIV. DIST. 3	97 117
It is intended to plug and	abandon the subjectiful be submitted by	7-15-97. CENVER AY 3 0 1957 CON. DIV. DIST. 3	97 117
It is intended to plug and wellbore diagram wi	abandon the subjectiful be submitted by DE M O[[] foregoing is true	7-15-97. CENVER AY 3 0 1957 CON. DIV. DIST. 3	97 E. 23 P. 1 3: 14 070 F. L. 123 P. 1 3: 14
It is intended to plug and wellbore diagram wi	abandon the subject of the submitted by	T-15-97. CENTED AY 3 0 1997 COM. DIV. DIST. 3	97 E. 23 P. 1 3: 14 070 F. L. 123 P. 1 3: 14