Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

DISTRICT II P.O. Box DD, Artesia, NM 88210

2040 Pacheco St. Santa Fe, NM 87505

	WELL API NO.
	30-045-27478
5.	INDICATE TYPE OF LEASE
	STATE FEE

1000 Rio Brazos Rd., Aztec, NM 87410		es		OIL & GAS LEASE NO.			
			B 112	240-75			
SUNDRY NOTICES AND REPORTS (ON WE	LLS					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DIFFERENT RESERVOIR. USE "APPLICATION"	DEEPE	NOR-PLUG BACK TO A	7. LEASE	NAME OR UNIT AGREEMENT N	AME		
(FORM C-101) FOR SUCH PROPOSA	ALS.)	罗巴达国际国际	FC St	ate Com			
1. TYPE OF WELL:		Man					
OIL WELL GAS WELL OTHER		MAY 2 4 1999	<i>]</i>				
2. NAME OF OPERATOR	<u></u>	\nn o-	8. WELL N	Ю.			
CONOCO INC.	<u> </u>	OUL COM DOWN	#4				
3. ADDRESS OF OPERATOR		E TENO	-	IAME OR WILDCAT			
10 DESTA DR., SUITE 100W, MIDLAND, TX 7970 4. WELL LOCATION	<u> 15-4500</u>	5000 B	Basin	Fruitland Coal			
Unit Letter \underline{H} : 1340' Feet From The NORTH Line and	800'	Feet From The <u>EAST</u> Line	:				
Section <u>36</u> Township <u>31N</u> Range <u>09W</u> NMPM <u>San</u>	uluan (County					
		her DF, RKB, RT, GR, etc.)					
IO. ELEVATION (S	6503						
11. Check Appropriate Box to In		lature of Notice, Report, or O	ther Data				
NOTICE OF INTENTION TO:	iologio i			REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON	$\overline{}$				$\overline{}$		
		REMEDIAL WORK		ALTERING CASING	\Box		
TEMPORARILY ABANDON CHANGE PLANS [COMMENCE DRILLING OPNS.		PLUG AND ABANDONMENT			
PULL OR ALTER CASING		CASING TEST AND CEMENT JO	BS 🗌				
OTHER:		OTHER: Stringshot Proce	dure		\square		
12. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all	pertinent i	details, and give pertinent dates, inc	luding estima	ated date of starting any proposed	work)		
SEE RULE 1103.					•		
5/10/99 Road rig to location, spot rig and equipment. SDFD							
Toda ng to location, sporing and equipment. SDI D							
5/11/99 Rig up pulling unit, Pressure test tbg. to 500 #. Held OK. Rig up for rods. Unseated pump, POOH with 129 - 3/4" rods, 2- K bars							
and pump. NDWH, NUBOP. Pull off tbg. hanger, RIH with one joint of 2 7/8" tbg. Tag fill at 3329'. POOH with 600' of 2 7/8" tbg. Pull tbg.							
above perfs. SDFN							
5/12/99 Open well to pit, rig up wireline. Made 6 runs wit	414		0401 0 1				
3244', 4th 3149' to 3164', 5th 3136' to 3149', 6th 3080' to 3088'. All shot under lubicator. RD wireline. RIH with tbg. tag up on fill at 3329'. No new fill. Land tbg at 3324'. NDBOP, NUWH. RIH with rebuilt pump. 2-K bars and 129- 3/4" rods. Change out stuffing box and radigan. Load							
tbg, stroke pump to 400#.		1 Dai 0 and 120 0/4 1000. (onange of	at staining box and radigat	i. Loau		
5 <u>-13-99</u> Rig down pulling unit. Move off to next location.							
I haraby and it, that the information shours is translational to the state of the s							
I hereby certify that the information above is true and complete to the best of my known	owledge a	nd belief.					
SIGNATURE:	TITLE:	AGENT FOR CONOCC	INC.	DATE <u>5-20-99</u>			
TYPE OR PRINT NAME: VERLA JOHNSON							
THE CATAINT NAME. VEILE GOTTINOON	<u>_</u>	TELEPHONE NO. (505) 324-396	<u> </u>				
(This space for State Use)	1	SOUTH OH .		MAY 24 199	Q		
APPROVED BY ORIGINAL SIGNED BY CHAPLIE T. PERFIN	TITLE	PEPUTY OIL & GAS INSPECT	OR, DIST.	#TATE	J		
CONDITIONS OF APPROVAL, IF ANY:			7 7 9 1.				